CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877797
Transaction Date	19 Oct 2026, 17:42:56
Site Name	840 - Emirates Auctions
Transaction Number	76181050 (CC10006) (CC10006)



Vehicle Details

Chassis Number	2G1F91E32E*******
Specification	GCC Specification
Make	Chevrolet
Model	Camaro
Model Year	2014
Color	Yellow
Mileage	364724 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.E Bonnet	STAY SHOCK WEAK , NOT WORKING , LEFT SIDE DAMAGE	غطاء المحرك
01.F Pillars	BOTH SIDE DOOR PILLAR , WHEEL ARCH REPAIRED	القوائم
01.G Trunk	NOT OPENING	صندوق
01.H Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	FRONT LEFT SIDE MINOR DENT	الشاسيه
02.B Chassis Number	DOOR POST VIN STICKER PORTION DAMAGE	رقم القاعدة
03 Engine Condition		المحرك
03.A Mount	BUSHES CUT	كرسي
03.B Engine Visual Condition	REFITTED ,OIL LEAK, SHAKING ,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGE , FRONT RIGHT ADJUSTABLE SWICTH NOT WORKING	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	JERKING, REFITTED ,OIL LEAK.PARTS RUSTY	الحالة النظريه للجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
07.B Tail Light	LENS GETTING FADED PORTION CRACK	الضوء الخلفي
07.C Fog light	RIGHT SIDE DAMAGE	كشاف الضباب
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY	اخري
09.B AC Condition	NOT COOLING	المكيف
09.C Power Window Switch And Glass	RIGHT SIDE SWITCH NOT WORKING	مفتاح النافذه و الزجاج
09.D Dash Board	PORTION WORN OUT	لوحة القياده
09.E Door Panel	PORTIO DAMAGE	لوحة بطانة الباب
09.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae