CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899724
Transaction Date	28 Oct 2026, 15:01:03
Site Name	840 - Emirates Auctions
Transaction Number	20662204 (CC10006) (CC10011)



Vehicle Details

Chassis Number	VF33CRFNF4*******
Specification	Imported
Make	Peugeot
Model	307
Model Year	2004
Color	Silver
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT FIBER PAINT NOT CHECK	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED GETTING RUSTY	الصبغ
01.C Floor	UNDER FLOOR RUST PROOFED, PORTION DENT, PORTION RUSTY,BACK PANEL, QUATER PANEL REPAIRED	الارضية
01.D Bumper	MISALIGN SCRATCHES	دعامية
01.E Windshield	CRACKED	زجاج
01.F Pillars	RIGHT SIDE DOOR PILLAR ROCKER PANEL PORTION REPAIRED REPAINTED	القوائم
01.G Other	FRONT FENDER FRAME, BUMPER FRAME, RADITOR SUPPORT REPAIRED	اخري
01.H Trunk	NOT OPEN	صندوق
01.I Sign of front accident		وجود مؤشر لحادث في المقدمة
01.J Sign of back accident		وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	OK	الشاسيه
03 Engine Condition		المحرك
03.A Mount	BUSHES CUT	كرسي
03.B Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECK, REFITTED, OIL WET, PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	EXTRA COVER PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECK, REFITTED, OIL WET, PARTS RUSTY	الحالة النظريه للجير
05.B Gear Box Mount	BUSH CRACKED	كرسي الجير
05.C Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	CRACKED EXPIRED	الاطار الامامي
06.B Rear Tyre	CRACKED EXPIRED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED ALL LIGHT NOT CHECK	الاضاءة الرئيسية
07.B Tail Light	FADED CRACKED	الضوء الخلفي
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخري
08.B Mirror	CENTER MISSING	المرايا
08.C AC Condition	NOT CHECK	المكيف
08.D Roof Light	DAMAGED	أنارة السقف
08.E Dash Board	DISPLAY DAMAGED	لوحة القياده
08.F Roof Ceiling	LOOSE	بطانه السقف
08.G Odometer reading	NOT CHECK	قراءة عداد المسافات
08.H Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.I Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.J Gear Shifting Lever	KNOB WORN OUT,DUST COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae