



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 08 Nov 2022, 10:48:58 |
| Transaction Number | 20792529 (CC10009) | Queue Number | 619103 |



| | |
|------------------|--------------------------|
| Chassis Number | 1HGCV1F3XLA090067 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Honda |
| Model | Accord |
| Model Year | 2020 |
| Color | White |
| Mileage | 67676 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 4 |
| Specification | Imported |

| DEFECT | REMARKS | |
|------------------------------------|---|----------------------------|
| 01 Tires and Rims Condition | | الاطارات |
| 01.A Rear Tyre | BOTH SIDE 2020 CRACKED | الاطار الخلفي |
| 01.B Front Tyre | BOTH SIDE 2021/2020 CRACKED | الاطار الامامي |
| 02 Body | | جسم المركبة |
| 02.A Pillars | LEFT SIDE DOOR PILLAR OUTER DOOR POST ROCKER PANEL BOTH SIDE QUARTER PANEL REPAIRED | القوائم |
| 02.B Paint | BODY REPAINTED PORTION REPAIRED , MINOR DENTS SCRATCHES | الصبغ |
| 02.C Sign of front accident | | وجود مؤشر لحادث في المقدمة |
| 02.D Sign of side accident | | وجود مؤشر لحادث في الجانب |
| 02.E Sign of back accident | | وجود مؤشر لحادث في الخلف |
| 02.F Roof | ROOFRAILL PORTION REPAIRED REPAINTED | السقف |
| 02.G Other | FRONT LEFT SIDE FENDER FRAME WHEEL ARCH REAR RIGHT SIDE QUARTER PANEL REPAIRED | اخرى |
| 03 Transmission Condition | | الجير |
| 03.A Road Test | NOT CHECKED | فحص علي الطريق |
| 03.B Visual Gear Box Condition | GEAR BOX WELDED REPAIRED ,MINOR OIL LEAK | حالة الجير النظري |

| DEFECT | REMARKS | |
|------------------------------|---|------------------------|
| 03.C Gear Box Mount | MOUNT RUBBER CUT | كرسي الجير |
| 04 Engine Condition | | المحرك |
| 04.A Visual Engine Condition | MINOR OIL LEAK | حالة المحرك النظري |
| 04.B Mount | MOUNT RUBBER CUT | كرسي |
| 05 Suspension System | | ممتص الصدمات |
| 05.A Arms | LOWER ARM BUSHES CRACKED | ازرع |
| 05.B Ball Joint | BOOT CUT | مفصل كروي |
| 06 Chassis Condition | | الشاسي |
| 06.A Chassis | FRONT LEFT SIDE CHASSIS BEND , REAR RIGHT SIDE CHASSIS EXTENSION REPAIRED | الشاسيه |
| 07 Lights | | الاضاءة |
| 07.A Warning Light | WARNING LIGHT ON DISPLAY | ضوء تحذير |
| 08 Interior Condition | | الحاله الداخليه |
| 08.A AC Condition | OK | المكيف |
| 09 Steering Condition | | المقود |
| 09.A Steering Oil | MINOR OIL LEAK | زيت المقود |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

| | |
|--------------------------|-----------------------|
| Plate Details : | -- |
| Chassis No : | 1HGCV1F3XLA090067 |
| Vehicle Make : | HONDA |
| Vehicle Model : | ACCORD |
| Vehicle Class : | Light Vehicle |
| Body Type : | SALOON |
| Fuel : | Benzene |
| Color : | White |
| Drive Direction : | -- |
| Dimensions : (H x W x L) | -- x -- x -- |
| Current Odometer : | 67678 Kms. |
| Origin : United States | Model Year : 2020 |
| Gear Type : Automatic | Engine Size : 1800 CC |
| Engine No : NIL | Horse -- |
| Axles No : 2 | Power : |
| No Of 4 | Cylinders : 4 |
| Doors : | No Of Seats : 5 |
| G. V. W. : 2000 Kgs. | Empty 1500 Kgs. |
| | Weight : |

| | | | |
|---------------------------|---------------------|--------------|-------|
| Certificate Number : | 5-TAS-2022-18099577 | | |
| Inspection Date : | 14-11-2022 | | |
| Certificate Print Date : | 14-11-2022 | | |
| Services : | Registration Test | | |
| Vehicle Testing Partner : | Tasjeel | | |
| Vehicle Testing Center : | Tasjeel Al Aweer | | |
| Total Time Taken : | 5 min 36 sec | | |
| Appointment Ref Number : | -- | | |
| Start Time : | 21:38 | End Time : | 21:44 |
| Lane : | 02 | Token No. : | 352 |
| Attempt : | 2 | Prints No. : | 1 |

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

| | | | |
|-------------------|------------------------|--------------------|---------------------------|
| | | | |
| 13535 KM | 962 L | 3281 AED | 2.3 ton |
| Distance per year | Fuel consumed per year | Fuel cost per year | Carbon footprint per year |

Inspection Remarks: FRONT BUMPER,BULK HEAD,FENDER,FENDER FRAME REPAIRED.front left wheel housing ,fender frame minor dent

Payment Details

| | | | |
|---|-----------------------------------|--------------------------------|--|
| Inspection Performed by 34600 2151 2151 | Payment Method Cash | Transaction Number 18099577 | Service Fees AED 70 Collected on 14/11/2022 |
| Parking Slot No -- | Service Name Registration Test | Attempt 2 | Received by Bajurdeen Abdul Gafoor |

- This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

