

Queue Number

2819193

Transaction Date

30 Sep 2026, 14:54:02

Site Name

840 - Emirates Auctions

Transaction Number

40375924 (CC10008) (CC10025)



Vehicle Details

Chassis Number	WBA5B1102F*****
Specification	GCC Specification
Make	BMW
Model	535 i
Model Year	2015
Color	Black
Mileage	254200 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE REPAINTED PORTION REPAIRED REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER BODY FULLY COVERED CHECKED VISIBLE AREA ONLY ,SIGN OF WATER EFFECT	الارضية
01.E Bumper	MISALIGN , HOOK COVER MISSING	دعامية
01.F Trunk	FRONT SWITCH FADED , LOGO MISSING	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA / OK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK ,COMPONENTS REFITTED	الحالة النظرية للمحرك
------------------------------	-------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION CRACK , BACK COVER BRACKET PORTION DAMAGED LOOSE	حالة المقاعد
---------------------	--	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	PARTS GETTING RUSTY ,MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED , SWITCH MELTED	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE CRACK	الضوء الخلفي
08 Interior Condition		الحالة الداخلية
08.A Other	FRONT CIGARETTE CONSOLE BOX COVER LOOSE	اخرى
08.B AC Condition	OK , SWITCH FADED	المكيف
08.C Floor Matting	DIRTY	فرش الأرضيه
08.D Roof Ceiling	LOOSE	بطانه السقف
08.E Door Panel	WORN OUT , PORTION MELTED	لوحة بطانة الباب
08.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae