CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2968190
Transaction Date	13 Nov 2026, 15:08:22
Site Name	840 - Emirates Auctions
Transaction Number	13153143 (CC10009) (CC10019)



Vehicle Details

Chassis Number	WBAKR6101E*******
Specification	GCC Specification
Make	BMW
Model	X5
Model Year	2014
Color	Black
Mileage	135198 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE FIBER PAINT NOT CHECKED & REAR BOTH SIDE REPAINTED,PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Doors	REPAINTED,PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COMPLETELY COVERED NOT VISIBLE PROPERLY	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	REPAINTED,PORTION REPAIRED	غطاء المحرك
01.H Trunk	COVER PANEL PORTION MISSING	صندوق
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	REMOVE ALL UNDER FLOOR CHASSIS COVERS FOR RECHECK PROPERLY	اخري
02.C Chassis Number	STICKER PORTION WORN OUT	رقم القاعدة
03 Engine Condition		**المحرك**
03.A Smoke	WHITE SMOKE	دخان
03.B Engine Visual Condition	OIL LEAK REFITTED,SHAKING	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**

Condition	Remarks	الحالة
04.A Seat Condition	DRIVER SEAT SIDE COVER PORTION DAMAGED,LOOSE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED,MINOR JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
08.B Other	SUSPENSION REFITTED	اخري
09 Interior Condition		الحاله الداخليه
09.A Roof Ceiling	PORTION LOOSE	بطانه السقف
09.B Door Panel	PORTION LOOSE	لوحة بطانة الباب
09.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae