CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899713
Transaction Date	27 Oct 2026, 13:00:46
Site Name	840 - Emirates Auctions
Transaction Number	79414086 (CC10021) (CC10021)



Vehicle Details

Chassis Number	1N4AL3AP0F*******
Specification	Imported
Make	Nissan
Model	Altima
Model Year	2015
Color	Grey
Mileage	200152 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS , SUSPENTION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN , PORTION DAMAGE , TOW HOOK COVER MISSING	دعامية
01.E Sign of back accident	BACK PANEL, QUATER PANEL, COMPARTMENT REPAIRED	وجود مؤشر لحادث في الخلف
01.F Vehicle Color	SILVER	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	REAR BOTH SIDE CHASSIS EXTENSION END REPAIRED , DENT	الشاسيه
03 Engine Condition		المحرك
03.A Mount	UPPER MOUNT BUSHES CUT	كرسي
03.B Engine Visual Condition	PARTS REFITTED GETTING RUSTY , ABNORMAL NOISY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY , MINOR JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED & CRACK	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
09.B AC Condition	NOT COOLING	المكيف
09.C Dash Board	PORTION WORN OUT	لوحة القياده
09.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
09.E Door Panel	PORTION DAMAGE	لوحة بطانة الباب
09.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	PORTION WORN OUT , SHIFTER COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae