



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>27 Sep 2021, 18:02:39</b>
Transaction Number	<b>64527098 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>5N1DR2M50LC575075</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Pathfinder</b>
Model Year	<b>2020</b>
Color	<b>White</b>
Mileage	<b>14432 N/A</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	REPAIRED & REPAINTED	مدكار
01.B Paint	BODY TOTALY PORTION REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Doors	REPAIRED & REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	REPAINTED	دعامية
01.F Roof	PORTION REPAIRED, REPAINTED	السقف
01.G Bonnet	REPAIRED & REPAINTED	غطاء المحرك
01.H Other	FRONT FENDER FRAME, APRON , WHEEL HOUSING , BUMPER FRAME , RADITOR SUPPORT , BULK HEAD REPAIRED	اخرى
01.I Pillars	LEFT SIDE PILAR REPAIRED	القوائم
<b>02 Chassis Condition</b>		<b>الشاسي</b>
02.A Chassis	FRONT CHASSIS. OUTER SKIRT REPAIRED	الشاسيه
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Other	OIL LEAK	اخرى
<b>04 Seats Condition</b>		<b>المقاعد</b>
04.A Other	OK	اخرى
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Gear Box	OK	الجير

DEFECT	REMARKS	
<b>06 Lights</b>		<b>الاضاءة</b>
06.A Head Light	OK	الاضاءة الرئيسية
06.B Other	OK	اخرى
<b>07 Brake Condition</b>		<b>الفرامل</b>
07.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
<b>08 Interior Condition</b>		<b>الاجزاء الداخلية</b>
08.A Other	DASHBOARD COVER CRACKED	اخرى
08.B Mirror	OK	المرايا
08.C AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Plate Details :	--
Chassis No :	5N1DR2M50LC575075
Vehicle Make :	NISSAN
Vehicle Model :	PATHFINDER
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	14434 Kms.
Origin :	United States
Model Year :	2020
Gear Type :	--
Engine Size :	3500 CC
Engine No :	VQ3508817...
Horse Power :	--
Axles No :	2
Cylinders :	6
No Of Doors :	4
No Of Seats :	7
G. V. W. :	Empty Weight : 1800 Kgs. 2500 Kgs.

Certificate Number :	5-TAS-2021-15151472
Inspection Date :	03-10-2021
Certificate Print Date :	03-10-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	11 min 7 sec
Appointment Ref Number :	--
Start Time :	15:53
End Time :	16:04
Lane :	01
Token No. :	171
Attempt :	1
Prints No. :	1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate in 12 Months)

3608 KM	372 L	603 AED	0.9 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
0 %	0 %	27 %	0.17 %

## Vehicle on Petrol HC

### Reading

9 PPM VOL

Inspection Remarks: FRONT LEFT FENDER FRAME REPAIRED.ENGINE OIL MINOR LEAK.

## Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
8008085 37084	Cash	15151472	AED 170 Collected on 03/10/2021
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

