CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2990414
Transaction Date	14 Nov 2026, 13:03:56
Site Name	840 - Emirates Auctions
Transaction Number	66159101 (CC10013) (CC10011)



Vehicle Details

Chassis Number	SALGS2RE4K*******
Specification	Imported
Make	Range Rover
Model	Vogue
Model Year	2020
Color	White
Mileage	114251 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY TOTALLY STICKER PAINT NOT CHECK PROPERLY STICKER PORTION LOOSE FADED,PORTION REPAIRED REPAINTED	الصبغ
01.C Doors	LEFT SIDE REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED,CHECKED VISIBLE AREA ONLY	الارضية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Pillars	LEFT SIDE DOOR PILLARS ROCKER PANEL REPAIRED,SUSPUCT REPLACED	القوائم
01.H Trunk	SHOCK WEAK,LUGGAGE SHADE MISSING	صندوق
01.I Fuel Tank	DENT	خزان الوقود
01.J Vehicle Year Model	2019	سنة صنع المركبة
01.K Vehicle Model	RANGER ROVER SUPERCHARGED	طراز المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED,CHECKED VISIBLE AREA FRONT RIGHT SIDE OUTER MINOR DENT	الشاسيه
02.B Chassis Number	VIN LAMINATED	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	MINOR OIL LEAK , COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	FRONT NECK REST LOOSE LEFT SIDE ADJUSTMENT NOT WORKING PROPERLY	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR OIL LEAK , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED,BRACKET DAMAGED REPAIRED	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE PORTION CRACK	الضوء الخلفي
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.D Brake Light	RIGHT SIDE NOT WORKING	نور الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES SIGN OF MINOR DRY CRACK	ازرع
08.B Other	SUSPENSION PARTS REFITTED	اخري
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CUP HOLDER SLIDING COVER STUCK,INTERIOR MODIFIED PARTS REFITTED GETTING RUSTY SIGN OF FLOODED	اخري
09.B AC Condition	OK	المكيف
09.C Power Window Switch And Glass	FRONT RIGHT SIDE SWITCH LOOSE NOT WORKING	مفتاح النافذه و الزجاج
09.D Engine Start Button	REMOTE WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae