

Queue Number	2672859	Transaction Date	24 Aug 2026, 14:43:36
Site Name	840 - Emirates Auctions	Transaction Number	53385761 (CC10009) (CC10012)



Vehicle Details

Chassis Number	SCBEA5ZA2E*****
Specification	GCC Specification
Make	Bentley
Model	Flying Spur
Model Year	2014
Color	White
Mileage	19174 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	12

Condition	Remarks	الحالة
-----------	---------	--------

01 Body		جسم المركبة
01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION RUSTY	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS NOT VISIBLE	الارضية
01.F Roof	ROOF RAIL REPAIRED	السقف
01.G Bonnet	SHOCK WEAK	غطاء المحرك
01.H Trunk	MISALIGN , SHOCK WEAK , NOT WORKING , AUTO NOT WORKING	صندوق
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	MINOR OIL LEAK, PARTS REFITTED ,PARTS GETTING RUSTY	الحالة النظرية للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	OIL WET, MINOR JERKING ,PARTS GETTING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Other	ELECTRIC FAULT	اخرى
06.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONY	دواسة الفرامل
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR REFITTED ,INTERIOR PARTS GETTING RUSTY ,SIGN OF WATER FLOODED	اخرى
08.B AC Condition	OK , FRONT DISPLAY , BUTTON ADJUSTMENT NOT WORKING	المكيف
08.C Floor Matting	REFITTED	فرش الأرضية
08.D Audio	NOT WORKING	صوتيات
08.E Dash Board	LEATHER REFLACED	لوحة القيادة
08.F Sunroof	NOT WORKING	فتحت سقف
08.G Gear Shifting Lever	DUST COVER DAMAGED	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae