



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>26 Dec 2021, 17:58:05</b>
Transaction Number	<b>13292610 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JN8AY2NY3F9120875</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Patrol</b>
Model Year	<b>2015</b>
Color	<b>White</b>
Mileage	<b>236282 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	FRONT RIGHT SIDE PORTION REPAIRED & REPAINTED	مدكار
01.B Doors	FRONT RIGHT SIDE REPAINTED	أبواب
01.C Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.D Bonnet	PORTION REPAINTED	غطاء المحرك
01.E Bumper	REPAINTED	دعامية
01.F Door Handle & Lock	FRONT LEFT SIDE OUTER COVER MISSING	مقابض الأبواب والأقفال
01.G Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS FRAME GETTING RUSTY	صدأ
<b>02 Interior Condition</b>		<b>الحالة الداخلية</b>
02.A Sun Visor	LEFT SIDE BROCKEN	حاجب الشمس
02.B AC Condition	OK	المكيف
02.C Mirror	OK	المرآيا
<b>03 Seats Condition</b>		<b>المقاعد</b>
03.A Seat Condition	OK	حالة المقاعد
03.B Seat Belt	FRONT RIGHT SIDE NOT WORKING	حزام الأمان

DEFECT	REMARKS	
<b>04 Wipers and Arms</b>		<b>المساحات</b>
04.A Wiper Arm & Blade	WORN OUT	ازرع المساحات والشفرات
04.B Other	WATER TANK COVER MISSING	اخرى
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Front Tyre	BOTH SIDE 2020/2019	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED, RUSTY	ازرع
06.B Shock Absorber	LEAKING	ممتص الصدمات
<b>07 Chassis Condition</b>		<b>الشاصي</b>
07.A Chassis	CHASSIS FRAME RUSTY	الشاسيه
<b>08 Engine Condition</b>		<b>المحرك</b>
08.A Engine Condition	OK	حالة المحرك
08.B Smoke	BLACK SMOKE	دخان
<b>09 Transmission Condition</b>		<b>الجير</b>
09.A Road Test	NOT CHECK	فحص علي الطريق
09.B Gear Box	OK	الجير
09.C DIFFERENTIAL	FRONT SIGN OF LEAK	الدفرنشئل
<b>10 Steering Condition</b>		<b>المقود</b>
10.A Axel	AXL CASE LEAKING	اكسلات
<b>11 Lights</b>		<b>الاضاءة</b>
11.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.