



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	10 Oct 2021, 17:42:54
Transaction Number	40031614 (CC10006)	Queue Number	312309



Chassis Number	SALVA2BG9DH805651
Engine Number	
Vehicle Class	Car
Manufacturer	Range Rover
Model	Evoque
Model Year	2013
Color	Silver
Mileage	0 N/A

DEFECT	REMARKS	
<b>01 Body</b>		جسم المركبة
01.A Paint	BODY PORTION REPAINTED	الصبغ
01.B Fenders	REAR RIGHT FENDER REPAINTED&FRONT FENDER FIBER PAINT CANNOT CHECK	مدكار
01.C Doors	RIGHT DOOR REPAINTED	أبواب
01.D Bumper	REPAINTED	دعامية
01.E Floor	UNDER FLOOR COVERD	الارضية
<b>02 Seats Condition</b>		المقاعد
02.A Other	OK	اخرى
<b>03 Tires and Rims Condition</b>		الاطارات
03.A Front Tyre	BOTH SIDE 2018 CRACKED	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2018 CRACKED	الاطار الخلفي
<b>04 Engine Condition</b>		المحرك
04.A Other	INTER COOLER PIPE REPAIRED & SMART SWITCH BATTERY DOWN ENGINE NOT START	اخرى
<b>05 Transmission Condition</b>		الجير
05.A Gear Box	OK	الجير
<b>06 Chassis Condition</b>		الشاسي
06.A Chassis	OK	الشاسيه

## DEFECT

## REMARKS

07 Lights

الاضاءة

07.A Head Light

FADED

الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.