CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877727
Transaction Date	20 Oct 2026, 10:41:46
Site Name	840 - Emirates Auctions
Transaction Number	60382173 (CC10010) (CC10010)

Vehicle Details

Chassis Number	WVWAR7A35F*******
Specification	GCC Specification
Make	Volkswagen
Model	Passat
Model Year	2015
Color	White
Mileage	234795 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	5

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	RIGHT SIDE REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.E Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.F Fuel Tank	EXCESSIVE FUEL LEAKING. DRIPPING.	خزان الوقود
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
02.B Other	REMOVE FENDER UNDER COVER FOR INSPECTION .	اخري
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2021 EXPIRED CRACKED.	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2021 EXPIRED CRACKED.	الاطار الخلفي
05.C Rims Condition	DENTS SCRATCHES .	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
06.B Tail Light	PORTION CRACKED.	الضوء الخلفي
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	LEAK .	ممتص الصدمات
07.B Arms	BUSHES CRACKED.	ازرع
08 Steering Condition		المقود
08.A Steering Boot	CUT .	ربلة المقود
08.B Steering Box	OIL LEAK .	جهاز المقود
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED.	اخري
09.B Roof Light	GLASS HOLDER LOOSE.	أنارة السقف
09.C Roof Ceiling	PORTION LOOSE	بطانه السقف
09.D Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
09.E Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
09.F Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae