



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	06 May 2022, 11:34:05
Transaction Number	27924197 (CC10008)	Queue Number	312309



Chassis Number	1GKEV33738J275549
Engine Number	
Vehicle Class	Car
Manufacturer	GMC
Model	Acadia
Model Year	2008
Color	Black
Mileage	264435 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف
01.B Mirror	FOLDING NOT WORKING & RIGHT SIDE GLASS DAMAGED	المرايا
01.C Sun Visor	BOTH SIDE GLASS COVER MISSING	حاجب الشمس
01.D Other	HAND REST LEATHER WORN OUT	اخرى
02 Body		جسم المركبة
02.A Paint	BODY REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
02.B Fenders	REAR BOTH SIDE PORTION REPAIRED,REPAINTED	مدكار
02.C Doors	REAR RIGHT SIDE REPAIRED,REPAINTED	أبواب
02.D Trunk	REPAIRED,REPAINTED	صندوق
02.E Bonnet	REFITTED & SHOCK WEAK	غطاء المحرك
03 Seats Condition		المقاعد
03.A Seat Condition	DRIVER SEAT DAMAGED	حالة المقاعد
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2018	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي

DEFECT	REMARKS	
05 Transmission Condition		الجير
05.A Propeller Shaft	MIDDLE PROPELLER SHAFT REMOVED	ناقل الحركة
05.B DIFFERENTIAL	REAR DIFFRENTIAL OIL LEAK	الدفرنشل
05.C Road Test	NOT CHECK	فحص علي الطريق
05.D Visual Gear Box Condition	OIL LEAK	حالة الجير النظرى
06 Engine Condition		المحرك
06.A Visual Engine Condition	OIL LEAK	حالة المحرك النظرى
07 Suspension System		ممتص الصدمات
07.A Ball Joint	BOOT CUT	مفصل كروي
07.B Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
08 Steering Condition		المقود
08.A Axel	BOOT CUT	اكسلات
08.B Steering Oil	OIL LEAK	زيت المقود
08.C Tie Rod End	BOOT CUT	مؤخرة الروداد
09 Chassis Condition		الشاسي
09.A Chassis Extension	REAR EXTENSION END HAVE DENT	تمديدات الشاسي
09.B Chassis	OK	الشاسيه
10 Wipers and Arms		المساحات
10.A Wiper Arm &Blade	REAR MISSING	ازرع المساحات والشفرات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.