CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2938391
Transaction Date	03 Nov 2026, 12:51:00
Site Name	840 - Emirates Auctions
Transaction Number	84500598 (CC10009) (CC10019)



Vehicle Details

Chassis Number	JTEBU9FJ4P*******
Specification	GCC Specification
Make	Toyota
Model	Prado
Model Year	2023
Color	White
Mileage	191727 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	PORTION REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS COMPLETELY THICK RUST PROOFED	الارضية
01.E Roof	REPAINTED,PORTION REPAIRED	السقف
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETELY THICK RUST PROOFED,	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	PARTS REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	PARTS REFITTED MINOR JERKING,GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي

Condition	Remarks	الحالة
06 Lights		**الاضاءة**
06.A Tail Light	LEFT SIDE PORTION DAMAGED	الضوء الخلفي
07 Interior Condition		**الحاله الداخليه**
07.A Other	INETRIOR PARTS GETTING RUSTY SIGN OF FLOODED/ CENTER CONSOLE BOX COVER PORTION DAMAGED	اخري
07.B AC Condition	OK	المكيف
07.C Power Window Switch And Glass	FRONT RIGHT SIDE NOT WORKING	مفتاح النافذه و الزجاج
07.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
07.E Gear Shifting Lever	GEAR LOCK COVER MISSING & KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae