CAR CHECK

شهادة فحص مركبة
**Vehicle Test Certificate**

| | |
|---|---|
| Queue Number | 2934144 |
| Transaction Date | 03 Nov 2026, 17:00:12 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 51936903 (CC10021) (CC10021) |



**Vehicle Details**

| | |
|---|---|
| Chassis Number | KMHMG81C86******* |
| Specification | GCC Specification |
| Make | Hyundai |
| Model | Trajet |
| Model Year | 2006 |
| Color | White |
| Mileage | N/A NA |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 6 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | جسم المركبة |
| 01.A Paint | BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY | الصبغ |
| 01.B Rusty | UNDER BODY PARTS ,SUSPENSION GETTING RUSTY | صدأ |
| 01.C Floor | UNDER FLOOR PORTION DENTS, MUDDY | الارضية |
| 01.D Bumper | MISALIGN , PORTION DAMAGE | دعامية |
| **02 Chassis Condition** | | الشاصي |
| 02.A Chassis | CHASSIS COVERED,MUDDY,PORTION DENT | الشاسيه |
| **03 Engine Condition** | | المحرك |
| 03.A Engine Visual Condition | ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY | الحالة النظريه للمحرك |
| **04 Seats Condition** | | المقاعد |
| 04.A Seat Condition | PORTION WORN OUT | حالة المقاعد |
| **05 Transmission Condition** | | الجير |
| 05.A Gear Box Visual Condition | NOT CHECKED REFITTED OIL LEAK PARTS RUSTY | الحالة النظريه للجير |
| 05.B Road Test | NOT CHECKED | فحص علي الطريق |
| **06 Tires and Rims Condition** | | الاطارات |
| 06.A Front Tyre | BOTH SIDE CRACK | الاطار الامامي |

| Condition | Remarks | الحالة |
|---|---|---|
| 06.B Rear Tyre | BOTH SIDE CRACK | الاطار الخلفي |
| **07 Lights** | | الاضاءة |
| 07.A Head Light | LENS FADED, ALL LIGHTS NOT CHECKED | الاضاءة الرئيسية |
| **08 Brake Condition** | | الفرامل |
| 08.A Disc&Drum | RUSTY | دسك وطنابير الفرامل |
| **09 Suspension System** | | ممتص الصدمات |
| 09.A Arms | BUSHES CRACK | ازرع |
| 09.B Ball Joint | BOOT CUT | مفصل كروي |
| 09.C Stabilizer Bar And Link Rod | BOOT CUT | عمود التوازن و مثبت عمود التوازن |
| **10 Interior Condition** | | الحاله الداخليه |
| 10.A Other | INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED | اخري |
| 10.B AC Condition | NOT CHECK | المكيف |
| 10.C Dash Board | GLOVE BOX DAMAGED | لوحة القياده |
| 10.D Door Panel | WORN OUT | لوحة بطانة الباب |
| 10.E Steering Wheel and control buttons | WORN OUT | عجلة القيادة وازرار التحكم |
| 10.F Gear Shifting Lever | WORN OUT | ذراع نقل السرعات |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
**carcheck.ae/certificate**

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
**wecare@carscheck.ae**