



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	25 May 2023, 11:16:37
Transaction Number	30343706 (CC10008)	Queue Number	726411



Chassis Number	4T1BF1FK7CU028439
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Camry
Model Year	2012
Color	Black
Mileage	216105 Miles
Fuel Type	Petrol
No. Of Cylinders	4
Specification	Imported

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A Sun Visor	LOOSE	حاجب الشمس
01.B Roof Light	LOOSE,NOT WORKING	أنارة السقف
01.C Mirror	ADJUSTMENT NOT WORKING & CENTER VIEW MIRROR FADED	المرايا
01.D Dash Board	GLOVEBOX DAMAGED	لوحة القيادة
01.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
01.F Air Bag	RIGHT SIDE DAMAGED	وسائد هوائية
01.G Roof Ceiling	LOOSE&FRONT RIGHT SIDE GRIP HANDLE DAMAGED	بطانه السقف
01.H AC Condition	LOW COOLING	المكيف
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Rear Tyre	BOTH SIDE 2015,CRACKED,EXPIRED	الاطار الخلفي
02.B Front Tyre	BOTH SIDE 2018/2019,CRACKED	الاطار الامامي
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Pillars	DOOR PILLAR REPAIRED,SUSPECT CUT,RUSTY	القوائم
03.B Sign of side accident		وجود مؤشر لحادث في الجانب

DEFECT	REMARKS	
03.C Bonnet	REFITTED	غطاء المحرك
03.D Paint	BODY REPAINTED,PORTION REPAIRED,DENT,SCRATCHES,PORTION FADED	الصبغ
03.E Fenders	FRONT REFITTED	مدكار
03.F Bumper	MISALIGN,PORTION DAMAGED	دعامية
03.G Door Handle &Lock	FRONT BOTH SIDE CRAB HANDLE LOOSE & FRONT LEFTSIDE OUTER LOCK COVER MISSING	مقابض الأبواب والأقفال
03.H Sign of front accident		وجود مؤشر لحادث في المقدمة
03.I Floor	PORTION DENT & LOWER RADIATOR SUPPORT DAMAGED& REAR QUATER PANEL WHEEL ARCH REPAIRED	الارضية
03.J Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY .	صدأ
03.K Windshield	FRONT CRACKED	زجاج
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Other	ENGINE STARTING REMOTE BROKEN	اخرى
04.B Visual Engine Condition	OIL SUMB DENT	حالة المحرك النظرى
<b>05 Lights</b>		<b>الاضاءة</b>
05.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
05.B Tail Light	MINOR CRACKED	الادارة
05.C Head Light	LENS FADED,BRACKET BROKEN	الاضاءة الرئيسية
05.D Other	LIGHTS NOT WORKING PROPERLY	اخرى
05.E Brake Light	RIGHT SIDE NOT WORKING	نور الفرامل
<b>06 Transmission Condition</b>		<b>الجير</b>
06.A Visual Gear Box Condition	OIL SUMB DENT	حالة الجير النظرى
<b>07 Brake Condition</b>		<b>الفرامل</b>
07.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
<b>08 Chassis Condition</b>		<b>الشاسي</b>
08.A Chassis	FRONT LEFT SIDE CHASSIS END BEND ,OPEN	الشاسيه
<b>09 Suspension System</b>		<b>ممتص الصدمات</b>
09.A Arms	LOWER ARM BUSHES CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

