CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2970704
Transaction Date	10 Nov 2026, 11:53:57
Site Name	840 - Emirates Auctions
Transaction Number	18224822 (CC10010) (CC10010)



Vehicle Details

Chassis Number	KMJWA37R9G*******
Specification	GCC Specification
Make	Hyundai
Model	H1
Model Year	2016
Color	White
Mileage	366396 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED REPAINTED ,REAR LEFT SIDE QUARTER PANEL REPAINTED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	FLOOR ,RUNNING BOARD PORTION DENT .	الارضية
01.E Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.F Bonnet	REPAINTED REFITTED REPAIRED.	غطاء المحرك
01.G Trunk	PORTION REPAINTED REFITTED .	صندوق
01.H Fuel Tank	DENT ,FUEL LEAKING.	خزان الوقود
01.I Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.J Sign of back accident	BACK PANEL ,BUMPER FRAME DENT.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT CHASSIS END DENT ,CHASIS GETTING RUSTY PORTION COVERED.	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	WHITE	دخان
03.B Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	PORTION CUT .EXTRA COVER.	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 DRY CRACKED .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 DRY CRACKED .	الاطار الخلفي
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONGY.	دواسة الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK.	ممتص الصدمات
08.B Arms	BUSHES CRACKED,	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT .	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخري
10.B AC Condition	NOT COOLING , GRILL PORTION CUT .	المكيف
10.C Power Window Switch And Glass	FRONT LEFT SIDE POWER WINDOW NOT WORKING PROPERLY ,SWITCH LOOSE.	مفتاح النافذه و الزجاج
10.D Dash Board	PORTION CUT .	لوحة القياده
10.E Sun Visor	LOOSE.	حاجب الشمس
10.F Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae