



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	31 Aug 2021, 13:40:40
Transaction Number	21849783 (CC10007)	Queue Number	312309



Chassis Number	WBAZV8109BL392190
Engine Number	
Vehicle Class	Car
Manufacturer	BMW
Model	X5
Model Year	2011
Color	White
Mileage	100296

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	RIGHT SIDE BOTH REPAINTED	مدكار
01.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.C Doors	RIGHT SIDE BOTH DOOR REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bonnet	PORTION REPAIRED & HAVE BLACK STICKER	غطاء المحرك
01.F Roof	HAVE BLACK STICKER	السقف
01.G Other	REAR TRUNK RIGHT SIDE SHOCK BROCKEN & LEFT SIDE WEAK	اخرى
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS VISABLE AREA OK	الشاسيه
03 Seats Condition		المقاعد
03.A Other	OK	اخرى
04 Transmission Condition		الجير
04.A Propeller Shaft	POPELLAR SHAFT RUBBER CRACKED	ناقل الحركة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2017/2018 CRACKED & EXPIRED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2015/2016 CRACKED & EXPIRED	الاطار الخلفي

DEFECT	REMARKS	
06 Wipers and Arms		المساحات
06.A Other	WORN OUT	اخرى
07 Lights		الاضاءة
07.A Head Light	OK	الاضاءة الرئيسية
07.B Other	OK	اخرى
08 Brake Condition		الفرامل
08.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	FRONT BOTH SIDE LOWER ARMS BUSHES DRY CRACKED	ازرع
10 Steering Condition		المقود
10.A Steering Boot	BOOT LEAKING	ربلة المقود
10.B Tie Rod End	BUSHES CRACKED	مؤخرة الرودادات
11 Interior Condition		الاجزاء الداخلية
11.A Other	OK	اخرى
11.B Mirror	OK	المرايا
11.C AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.