

Queue Number 2899420

Transaction Date 23 Oct 2026, 15:28:35

Site Name
840 - Emirates AuctionsTransaction Number
61677004 (CC10013) (CC10011)

Vehicle Details

Chassis Number	WVGBC2BP9E*****
Specification	GCC Specification
Make	Volkswagen
Model	Touareg
Model Year	2014
Color	White
Mileage	108554 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE REPAIRED REPAINTED SKIRT PORTION DAMAGED,REAR LEFT REPAINTED PORTION REPAIRED,FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES	الصبغ
01.C Doors	FRONT LEFT SIDE PORTION REPAINTED,FRONT BOTH REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION COVERED DIRTY	الارضية
01.F Bumper	MISALIGN PORTION DAMAGED , HOOK COVER MISSING	دعامية

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Chassis Number	VIN CHECK ONLY DOOR POST STICKER	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL WET , COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	FRONT BOTH SEAT SIDE COVER PORTION DAMAGED	حالة المقاعد
---------------------	--	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظرية للجير
--------------------------------	---------------------	----------------------

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Wiper Arm &Blade	REAR BLADE MISSING	ازرع المساحات والشفرات
08 Lights		الاضاءة
08.A Head Light	RIGHT SIDE WASHER COVER MISSING	الاضاءة الرئيسية
08.B Tail Light	LEFT SIDE PORTION CRACKED	الضوء الخلفي
08.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES CRACK	ازرع
10 Interior Condition		الحالة الداخليه
10.A Other	REAR CIGARETTE LIGHTER PANEL COVER MISSING	اخرى
10.B Mirror	RIGHT SIDE NOT WORKING PROPERLE	المرايا
10.C AC Condition	NOT COOLING,SWITCH PORTION WORN OUT	المكيف
10.D Power Window Switch And Glass	FRONT BOTH SIDE SWITCH MAIN PORTION LOOSE RIGHT SIDE NOT WORKING PROPERLY , REAR LEFT SIDE CURTAIN LOCK COVER PORTION DAMAGED	مفتاح النافذه و الزجاج
10.E FFloor Matting	EXTRA FITTING	فرش الأرضيه
10.F Roof Ceiling	PORTION LOOSE	بطانه السقف
10.G Door Panel	LEATHER PORTION LOOSE	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on

للشكاوي والمقترحات يمكنك التواصل معنا عبر

