

Queue Number 2899801

Transaction Date 22 Oct 2026, 16:50:42

Site Name
840 - Emirates AuctionsTransaction Number
64292374 (CC10013) (CC10011)

Vehicle Details

Chassis Number	JTFHX02P5P*****
Specification	GCC Specification
Make	Toyota
Model	Hiace
Model Year	2023
Color	White
Mileage	174967 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Paint	BODY REPAINTED PORTION REPAIRED, EXCEPT ROOF, MINOR DENTS SCRATCHES, PORTION FADED RUSTY	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR RUNNING BOARD DENT PORTION RUSTY	الارضية
01.D Bumper	MISALIGN , PORTION CRACK PART MISSING	دعامية
01.E Trunk	LOGO MISSING	صندوق

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition المحرك

03.A Engine Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--------------------------------	-----------------------

04 Seats Condition المقاعد

04.A Seat Condition	PORTION DAMAGED , REAR MISSING , CABIN MODIFIED	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition الجير

05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
--------------------------------	--------------------------------	----------------------

05.B Road Test	NOT CHECKED	فحص علي الطريق
----------------	-------------	----------------

06 Tires and Rims Condition الاطارات

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE 2025 GETTING WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
07 Lights		الاضاءة
07.A Tail Light	RIGHT SIDE PORTION CRACK	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Leaf Spring	MISALIGN , BUSHES DRY CRACK	
08.C Arms	ARM BUSHES DRY CRACK	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B AC Condition	NO COOLING,GRILL PORTION LOOSE	المكيف
09.C Dash Board	PORTION WORN OUT	لوحة القيادة
09.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.E Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae