



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>09 Sep 2021, 16:50:48</b>
Transaction Number	<b>72432853 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>2GCRCPEC3K1152209</b>
Engine Number	
Vehicle Class	<b>Heavy</b>
Manufacturer	<b>Chevrolet</b>
Model	<b>Silverado</b>
Model Year	<b>2019</b>
Color	<b>Black</b>
Mileage	<b>11440</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	REPAIRED & REPAINTED	مدكار
01.B Paint	BODY TOTALY PORTION REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Doors	REAR RIGHT SIDE REPAIRED & REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS , CHASSIS GETTING RUSTY	صدأ
01.E Floor	REAR BOX REPAINTED	الارضية
01.F Bumper	REPAINTED	دعامية
01.G Bonnet	REPLACED	غطاء المحرك
01.H Other	FRONT FENDER FRAME, BUMPER FRAME , RADITOR SUPPORT , BULK HEAD & CROSSMEMBER REPAIRED OLD	اخرى
01.I Roof	REPAINTED	السقف
<b>02 Chassis Condition</b>		<b>الشاسي</b>
02.A Chassis	FRONT BOTH SIDE OLD REPAIRED GETTING RUSTY	الشاسيه
02.B Other	VIN NUMBER AREA GETTING RUSTY	اخرى
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Other	FILTER OIL LEAK	اخرى
<b>04 Brake Condition</b>		<b>الفرامل</b>
04.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>

DEFECT	REMARKS	
05.A Front Tyre	BOTH SIDE 2018	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Arms	FRONT BOTH SIDE LOWER ARMS BUSHES DRY CRACKED	ازرع
<b>07 Interior Condition</b>		<b>الاجزاء الداخلية</b>
07.A Other	OK	اخرى
07.B Mirror	OK	المرآيا
07.C AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Plate Details :	J 32929 Dubai Private
Chassis No :	2GCRCEPC3K1152209
Vehicle Make :	CHEVROLET
Vehicle Model :	SILVERADO
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	11365 Kms.
Origin :	Canada
Model Year :	2019
Gear Type :	--
Engine Size :	5300 CC
Engine No :	NIL
Horse Power :	--
Axles No :	2
Cylinders :	8
No Of Doors :	4
No Of Seats :	5
G. V. W. :	Empty Weight : 2200 Kgs. 2800 Kgs.

Certificate Number :	1-TAS-2021-14951326
Inspection Date :	06-09-2021
Certificate Print Date :	06-09-2021
Services :	Renewal Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	5 min 49 sec
Appointment Ref Number :	--
Start Time :	12:49
End Time :	12:55
Lane :	01
Token No. :	145
Attempt :	1
Prints No :	1

## Carbon footprint



Thank you! You are environment protector

## Vehicle Consumption ( last 12 Months )

5045 KM	520 L	843 AED	1.3 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
1 %	6 %	7 %	0 %

## Vehicle on Petrol HC

Reading  
1 PPM VOL

## Inspection Remarks:

ENGINE OIL MINOR LEAK.BODY MINOR SCRATCHES.FRONT BOTH SIDE CHASSIS REPAIRED FRONT BULKHEAD BUMPER&FRONT RIGHT SIDE FENDER REPLACED(OLD)

## Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
8008085 37084	Cash	14951326	AED 170 Collected on 06/09/2021
Parking Slot No	Service Name	Attempt	Received by
--	Renewal Test	1	Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.