



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	28 Dec 2021, 17:52:51
Transaction Number	48344926 (CC10006)	Queue Number	312309



Chassis Number	MROFX22G3F1142892
Engine Number	
Vehicle Class	Heavy
Manufacturer	Toyota
Model	Hilux
Model Year	2015
Color	White
Mileage	188976 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAIRED,REPAINTED ,DENT,SCRATCHES, PORTION RUSTY	الصبغ
01.B Bonnet	REPAINTED,PORTION REPAIRED	غطاء المحرك
01.C Fenders	FRONT RIGHT SIDE REPAINTED,PORTION REPAIRED&REAR CARRIER BOX REPAINTED, PORTION REPAIRED	مدكار
01.D Roof	REPAINTED,PORTION REPAIRED	السقف
01.E Bumper	FRONT REPAINTED,MISALIGN,FRONT GRILL MISSING	دعامية
01.F Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS ,FLOOR RUSTY	صدأ
01.G Windshield	FRONT WINDSHIELD CRACKED	زجاج
01.H Pillars	RIGHT DOOR PILLAR PORTION REPAIRED&PILLAR GETTING RUSTY	القوائم
01.I Other	ROCKER PANEL RUSTY,GETTING HOLE	اخرى
01.J Floor	ROCKER PANEL ,RUNNING BOARD RUSTY,GETTING HOLE	الارضية
02 Suspension System		ممتص الصدمات
02.A Leaf Spring	BUSHES WORN OUT	
02.B Shock Absorber	REAR RIGHT SIDE SHOCK ABSORBER OIL LEAK	ممتص الصدمات

DEFECT	REMARKS	
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
03.C Rims Condition	ALL RIMS GETTING RUSTY	حالة الجنوط
04 Battery Condition		حالة البطارية
04.A Battery Condition	NOT WORKING	حالة البطارية
05 Chassis Condition		الشاسي
05.A Chassis	CHASSIS FRAME RUSTY	الشاسيه
06 Engine Condition		المحرك
06.A Engine Condition	PART GETTING RUSTY	حالة المحرك
07 Transmission Condition		الجير
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B Gear Box	RUSTY& 4WD DUST BOOT LOOSE	الجير
07.C Propeller Shaft	RUSTY	ناقل الحركة
08 Seats Condition		المقاعد
08.A Seat Belt	REAR RIGHT SIDE NOT WORKING	حزام الأمان
08.B Seat Condition	FRONT RIGHT SIDE & REAR SEATS COVER DAMAGED	حالة المقاعد
09 Interior Condition		الحاله الداخليه
09.A AC Condition	OK	المكيف
09.B Steering Wheel and control buttons	WORN OUT&AIR BAG UINT LOOSE	عجلة القيادة وازرار التحكم
10 Lights		الاضاءة
10.A Tail Light	REAR BOTH SIDE LIGHTS LOOSE& RIGHT SIDE LIGHT BROKEN	الانارة
10.B Head Light	LENS FADED	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.