



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	15 Sep 2021, 14:17:39
Transaction Number	26121849 (CC10006)	Queue Number	312309



Chassis Number	WAUAY94LX7D071292
Engine Number	
Vehicle Class	Car
Manufacturer	Audi
Model	Q7
Model Year	2007
Color	White
Mileage	234978

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	REAR RIGHT SIDE REPAIRED, REPAINTED & LEFT SIDE BOTH PORTION REPAINTED	مدكار
01.B Paint	PORTION REPAIRED, REPAINTED	الصبغ
01.C Doors	REAR RIGHT SIDE REPAIRED, REPAINTED & LEFT SIDE BOTH PORTION REPAINTED	أبواب
01.D Floor	UNDER FLOOR COVERD	الارضية
01.E Bumper	REPAINTED	دعامية
01.F Bonnet	SHOCK WEAK	غطاء المحرك
02 Chassis Condition		الشاسي
02.A Chassis	OK	الشاسيه
03 Engine Condition		المحرك
03.A Other	OK	اخرى
04 Transmission Condition		الجير
04.A Gear Box	OIL LEAK	الجير
05 Seats Condition		المقاعد
05.A Other	OK	اخرى
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2018/2019	الاطار الامامي

DEFECT	REMARKS	
06.B Rear Tyre	BOTH SIDE 2017 CRACKED	الاطار الخلفي
07 Wipers and Arms		المساحات
07.A Other	OK	اخرى
08 Lights		الاضاءة
08.A Head Light	OK	الاضاءة الرئيسية
08.B Other	OK	اخرى
09 Brake Condition		الفرامل
09.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
10 Interior Condition		الاجزاء الداخلية
10.A Other	SLYDING ROOF NOT WORKING PROPERLY	اخرى
10.B Mirror	OK	المرايا
10.C AC Condition	NOT WORKING PROPERLY	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.