



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>05 May 2022, 18:01:32</b>
Transaction Number	<b>72491072 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>2C3CDXBG7KH745674</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Dodge</b>
Model	<b>Charger</b>
Model Year	<b>2019</b>
Color	<b>Green</b>
Mileage	<b>78374 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		<b>الاطارات</b>
01.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2020/2019	الاطار الخلفي
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Paint	BODY PORTION REPAINTED,MINOR DENT,SCRATCHES,	الصبغ
02.B Doors	LEFT SIDE REPAINTED	أبواب
02.C Roof	REPAINTED	السقف
02.D Floor	MIDDLE FLOOR REPAIRED	الارضية
<b>03 Interior Condition</b>		<b>الحاله الداخليه</b>
03.A AC Condition	OK	المكيف
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Visual Gear Box Condition	JERKING	حالة الجير النظرى
04.B Road Test	NOT CHECK	فحص علي الطريق
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	OK	حالة المحرك النظرى

## DEFECT

## REMARKS

## 06 Chassis Condition

الشاسي

06.A Chassis

OK

الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.