



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **22 Jan 2023, 13:54:43**
 Transaction Number **62826588 (CC10010)** Queue Number **657704**



Chassis Number **1N4BL24E39C117185**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Nissan**
 Model **Altima**
 Model Year **2009**
 Color **White**
 Mileage **001 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **6**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
01.B Sign of back accident		وجود مؤشر لحادث في الخلف
01.C Other	REAR BACK PANEL,QUATER PANEL,BUMPER FRAME,COMPARTMENT FLOOR REPAIRED,BEND	اخرى
01.D Floor	UNDER FLOOR RUST PROOFED,PORION DENT	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORION FADED,PORION RUSTY	الصبغ
02 Transmission Condition		الجير
02.A Gear Box Mount	CRACKED	كرسي الجير
02.B Visual Gear Box Condition	NOT CHECK,OIL LEAK	حالة الجير النظري
02.C Road Test	NOT CHECK	فحص علي الطريق
03 Interior Condition		الحالة الداخلية
03.A AC Condition	NOT CHECK,GRILL COVER PORTION CRACKED	المكيف
03.B Odometer reading	NOT CHECK	قراءة عداد المسافات
03.C Sun Visor	LEFT SIDE MISSING	حاجب الشمس

DEFECT	REMARKS	
03.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
03.E Roof Ceiling	PORTION LOOSE	بطانه السقف
04 Engine Condition		المحرك
04.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,OIL LEAK	حالة المحرك النظري
04.B Mount	CRACKED	كرسي
05 Tires and Rims Condition		الاطارات
05.A Rear Tyre	BOTH SIDE 2018 CRACKED , EXPIRED	الاطار الخلفي
05.B Front Tyre	BOTH SIDE 2018 CRACKED , EXPIRED	الاطار الامامي
06 Lights		الاضاءة
06.A Head Light	LENS FADED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية
07 Chassis Condition		الشاسي
07.A Chassis	REAR BOTH SIDE CHASSIS EXTENSION END DENT & CRASH BOX KINK	الشاسيه
08 Seats Condition		المقاعد
08.A Seat Condition	PORTION DAMAGED	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.