



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **09 Mar 2023, 15:27:41**  
 Transaction Number **34115302 (CC10009)** Queue Number **685099**



Chassis Number **JN1CA31D43T652381**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Nissan**  
 Model **Maxima**  
 Model Year **2003**  
 Color **--**  
 Mileage **001 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **6**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Paint	BODY PAINT NOT CHECKED PORTION RUSTY FADED DUSTY	الصبغ
01.B Bumper	MISALIGN PORTION DAMAGED	دعامية
01.C Floor	UNDER FLOOR PARTS CHASSIS SUSPENSION NOT CHECKED	الارضية
01.D Vehicle Color	WHITE	لون المركبة
01.E Other	VISUAL TEST ONLY	اخرى
<b>02 Chassis Condition</b>		<b>الشاسي</b>
02.A Chassis	CHASSIS NOT CHECKED	الشاسيه
02.B Chassis Number	VIN CHECKED ON STICKER ONLY	رقم القاعدة
<b>03 Interior Condition</b>		<b>الحاله الداخليه</b>
03.A Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
03.B Door Panel	PORTION LOOSE	لوحة بطانة الباب
03.C Dash Board	PORTION DAMAGED	لوحة القيادة
03.D AC Condition	NOT CHECKED	المكيف
<b>04 Transmission Condition</b>		<b>الجير</b>

DEFECT	REMARKS	
04.A Visual Gear Box Condition	NOT CHECKED	حالة الجير النظرى
<b>05 Tires and Rims Condition</b>		
05.A Front Tyre	CRACKED DATE NOT CHECKED	الاطارات الامامي
05.B Rear Tyre	CRACKED DATE NOT CHECKED	الاطارات الخلفي
<b>06 Engine Condition</b>		
06.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,	حالة المحرك النظرى
<b>07 Lights</b>		
07.A Head Light	LENS FADED	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.