

Queue Number 2869065

Transaction Date 15 Oct 2026, 13:06:24

Site Name
840 - Emirates AuctionsTransaction Number
88977731 (CC10026) (CC10026)

Vehicle Details

Chassis Number KNDJ23AU2M*****
 Specification Imported
 Make Kia
 Model Soul
 Model Year 2021
 Color Red
 Mileage 37091 Miles
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE & REAR LEFT SIDE REPAINTED PORTION REPAIRED & FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT LEFT SIDE REPAINTED & FRONT RIGHT SIDE , REAR LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY , SIGN OF FLOODED	صدأ
01.E Floor	UNDER FLOOR PORTION COVER MINOR DENT & LEFT SIDE RUNNING BOARD OUTER COVER MISSING	الارضية
01.F Bumper	MIALIGN , MINOR SCRATCHES , PORTION DAMAGE	دعامية
01.G Bonnet	REFITTED , REPAINTED	غطاء المحرك
01.H Sign of front accident	BUMPER FRAME , INNER FENDER FRAME , RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT RIGH SIDE CHASSIS REPAIRED , DENT	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	PART GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
---------------------	------------------	--------------

Condition	Remarks	الحالة
05 Transmission Condition الجير		
05.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition الاطارات		
06.A Front Tyre	FRONT BOTH SIDE 2021 EXPIRED & RIGHT SIDE DAMAGE	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021 CRACK EXPIRED & REAR LEFT SIDE DAMAGE	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES GETTING RUSTY	حالة الجنوط
07 Lights الاضاءة		
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System ممص الصدمات		
08.A Arms	BUSHES CRACK	ازرع
08.B Ball Joint	BOOT CRACK	مفصل كروي
08.C Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
09 Steering Condition المقود		
09.A Tie Rod End	BOOT CRACK	مؤخرة الرودادات
10 Interior Condition الحالة الداخليه		
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B AC Condition	OK	المكيف
10.C Power Window Switch And Glass	PORTION WORN OUT	مفتاح النافذه و الزجاج
10.D Dash Board	PORTION WORN OUT	لوحة القيادة
10.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae