

Queue Number

2899787

Transaction Date

22 Oct 2026, 17:01:35

Site Name

840 - Emirates Auctions

Transaction Number

71731060 (CC10010) (CC10010)



Vehicle Details

Chassis Number

JMYSTCS3A9*****

Specification

GCC Specification

Make

Mitsubishi

Model

Lancer

Model Year

2009

Color

Silver

Mileage

N/A Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.D Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.E Windshield	FRONT CRACKED.	زجاج
01.F Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاصي

02.A Chassis	REAR CHASSIS EXTENSION END REPAIRED DENT ,FRONT CHASSIS END DENT ,GETTING RUSTY.	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Mount	BUSHES CUT .	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	DIRTY PORTION LOOSE	حالة المقاعد
---------------------	---------------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظرية للجير
05.B Gear Box Mount	BUSHES CRACKED.	كرسي الجير
05.C Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	REXPIRED CRACKED DAMAGED	الاطار الامامي
06.B Rear Tyre	EXPIRED CRACKED WORN OUT .	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT	ربلة المقود
10.B Steering Box	OIL LEAK	جهاز المقود
11 Interior Condition		الحالة الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخرى
11.B Mirror	LOOSE FADED	المرايا
11.C AC Condition	NOT CHECKED.	المكيف
11.D Dash Board	PORTION LOOSE	لوحة القيادة
11.E Odometer reading	NOT CHECKED.	قراءة عداد المسافات
11.F Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
11.G Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.H Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae