

Queue Number

2837231

Transaction Date

05 Oct 2026, 13:20:20

Site Name

840 - Emirates Auctions

Transaction Number

23156494 (CC10010) (CC10010)



Vehicle Details

Chassis Number	4T1BB46K27*****
Specification	Imported
Make	Toyota
Model	Camry
Model Year	2007
Color	Silver
Mileage	N/A NA
Fuel Type	Hybrid
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REFITTED .	مدكار
01.B Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA ,	الارضية
01.E Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.F Bonnet	REFITTED .	غطاء المحرك
01.G Trunk	DENT MISALIGN ,NOT CLOSED.	صندوق
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD ,FENDER FRAME REPAIRED.	وجود مؤشر لحادث في المقدمة
01.I Sign of side accident	PILLAR OUTER PANEL,RUNNING BOARD,ROCKER PANEL REPAIRED.	وجود مؤشر لحادث في الجانب
01.J Sign of back accident	BACK PANEL ,QUARTER PANEL ,COMPARTMENT FLOOR REPAIRED,DENT .	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT CHASSIS REPAIRED DENT , GETTING RUSTY ,REAR CHASSIS EXTENSION BEND KINK DETACHED .,	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Mount	BUSHES CRACKED .	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER PORTION DAMAGED LOOSE.	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED WORN OUT PUNCTURE.	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED WORN OUT	الاطار الخلفي
06.C Spare Tire &Tools	MISSING.	الاطار الاحتياطي و العدة
07 Lights		الاضاءة
07.A Head Light	DAMAGED .	الاضاءة الرئيسية
07.B Tail Light	DAMAGED .	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY .	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK ,WEAK /.	ممتص الصدمات
09.B Arms	BUSHES CUT.	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT,	ربلة المقود
10.B Steering Box	OIL LEAK.	جهاز المقود
11 Interior Condition		الحالة الداخليه
11.A Other	INTERIOR CONDITION RUSTY. SIGN OF FLOODED	اخرى
11.B Mirror	LOOSE FADED.	المرايا
11.C AC Condition	NOT CHECKED .	المكيف
11.D Dash Board	LEATHER REPLACED PORTION LOOSE.	لوحة القيادة
11.E Roof Ceiling	PORTION LOOSE.	بطانه السقف
11.F Sun Visor	MISSING.	حاجب الشمس
11.G Odometer reading	NOT CHECKED .	قراءة عداد المسافات
11.H Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
11.I Air Bag	DAMAGED	وسائد هوائية
11.J Steering Wheel and control buttons	WORM OUT .	عجلة القيادة وازرار التحكم
11.K Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات



Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae