

TEST CERTIFICATE

Site Number
Transaction Number

Of Body

840-Emirates Auctions 20653802 (CC10006) Transaction Date

29 Dec 2021, 17:59:44

صدأ

الصبغ

Queue Number 312309

Chassis Number

JN6BE6DSXF9009802

Engine Number

Vehicle Class Heavy

Manufacturer Nissan

Model Urvan

Model Year 2015

Color White

Mileage **196447 Km**

Fuel Type Petrol

No. Of Cylinders

Specification GCC Specification

DEFECT REMARKS

OI Body		جسم المركبه
01.A Doors	FRONT BOTH SIDE & RIGHT SIDE SLYDING DOOR PORTION REPAIRED , REPAINTED	أبواب
01.B Fenders	FRONT RIGHT SIDE OUTER PANEL REPAINTED	مدكار

مدكار O1.B Fenders FRONT RIGHT SIDE OUTER PANEL REPAINTED مدكار O1.C Pillars RIGHT SIDE B/PILLAR OUTER PANEL REPAINTED

01.D Rusty UNDER BODY PARTS, SUSPENSION, CHASSIS, FLOOR

RUSTY

O1.E Floor FRONT RIGHT SIDE FLOOR, WHEEL ARCH REPAIRED الارضية

01.F Paint PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON

BODY

O2 Interior Condition الحاله الداخلية

O2.A AC ConditionOKالمكيفO2.B MirrorOKالمراياO2.C Power Window SwitchRIGHT SIDE NOT WORKINGمفتاح النافذه

الجير ll Usage of Transmission Condition

03.A Road Test NOT CHECK فحص علي الطريق

O3.B Gear Box OK

DEFECT	REMARKS	
04 Engine Condition		المحرك
04.A Engine Condition	MISFIRING	حالة المحرك
04.B Mount	LEFT SIDE BUSH CUT	كرسي
05 Seats Condition		المقاعد
05.A Seat Condition	FRONT RIGHT SIDE FOLDING SEAT PORTION DAMAGED	حالة المقاعد
O6 Lights		الاضاءة
06.A Head Light	ОК	الاضاءة الرئيسية
06.B Brake Light	CENTER COVER BROCKEN	نور الفرامل
07 Wipers and Arms		المساحات
07.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
08 Tires and Rims Condition		الاطارات
08.A Front Tyre	BOTH SIDE 2018 WORN OUT	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2018 WORN OUT	الاطار الخلفي
09 Chassis Condition		الشاصي
09.A Chassis	ОК	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.