

Queue Number

2877786

Transaction Date

21 Oct 2026, 12:23:03

Site Name

840 - Emirates Auctions

Transaction Number

38225687 (CC10010) (CC10010)



Vehicle Details

Chassis Number	KNAGM4A76F*****
Specification	Imported
Make	Kia
Model	Optima
Model Year	2015
Color	Grey
Mileage	183191 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR BOTH SIDE QUARTER PANEL REPAIRED REPAINTED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	BOTH SIDE DOORS REPAINTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Trunk	REPAINTED.	صندوق
01.G Sign of side accident	PILLAR OUTER PANEL WHEEL ARCH ROCKER PANEL REPAIRED.	وجود مؤشر لحادث في الجانب
01.H Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	REAR CHASSIS ,CHASSIS EXTENSION REPAIRED DENT . GETTING RUSTY ,FRONT CHASSIS COMPLETE COVERED	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظرية للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2022 CRACKED WORN OUT .	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2022 CRACKED WORN OUT .	الاطار الخلفي
05.C Rims Condition	DENTS SCRATCHES.	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED.	الاضاءة الرئيسية
06.B Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY	دواسة الفرامل
07.B Disc&Drum	PARTS RUSTY.	دسك و طنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CUT .	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT .	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخرى
10.B Mirror	CENTER MIRROR LOOSE	المرآيا
10.C AC Condition	LOW COOLING.	المكيف
10.D Power Window Switch And Glass	FRONT LEFT SIDE NOT WORKING.	مفتاح النافذه و الزجاج
10.E Audio	ANTENA DAMAGED	صوتيات
10.F Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae