

Queue Number

2855836

Transaction Date

12 Oct 2026, 09:48:19

Site Name

840 - Emirates Auctions

Transaction Number

50316177 (CC10026) (CC10026)



Vehicle Details

Chassis Number	5NPD74LF8H*****
Specification	Imported
Make	Hyundai
Model	Elantra
Model Year	2017
Color	White
Mileage	166247 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE & REAR RIGHT SIDE REPAINTED , FRONT RIGHT SIDE PORTION REPAINTED , FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAINTED , DENT SCRATCHES , PORTION FADED GETTING RUSTY	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED PORTION REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION COVER , RUNNING BOARD MINOR DENT , MUDDY	الارضية
01.F Bumper	MISALIGN , SCRATCHES PORTION FADED , TOW HOOK COVER MISSING	دعامية
01.G Bonnet	REPAINTED PORTION REPAINTED	غطاء المحرك
01.H Sign of front accident	BUMPER FRAME , INNDER FRAME , RADIATOR SUPPORT REPAINTED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	OK	الشاسيه
--------------	----	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ABNORMAL NOISY , SHAKING , GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	GETTING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	RIGHT SIDE 2023 & LEFT SIDE 2021 CRACK EXPIRED	الاطار الامامي
05.B Rear Tyre	LEFT SIDE 2022 & RIGHT SIDE 2023 ALL CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY	دواسة الفرامل
08 Interior Condition		الحالة الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخرى
08.B Mirror	CENTER VIEW MIRROR FADED	المرايا
08.C AC Condition	OK , VENT CHROME PANEL GETTING FADED	المكيف
08.D Steering Wheel and control buttons	PORTION WORN OUT , EXTRA COVER	عجلة القيادة وازرار التحكم
08.E Gear Shifting Lever	KNOB PORTION WORN OUT , SHIFTER COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae