



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>26 Sep 2022, 18:13:29</b>
Transaction Number	<b>62867345 (CC10006)</b>	Queue Number	<b>590298</b>



Chassis Number	<b>WBA5A310XFD742374</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>BMW</b>
Model	<b>520</b>
Model Year	<b>2015</b>
Color	<b>White</b>
Mileage	<b>206095 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A Door Panel	PORTION MELTED	لوحة بطانة الباب
01.B Audio	AUDIO DISPLAY NOT WORKING	صوتيات
01.C AC Condition	NOT WORKING	المكيف
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Visual Engine Condition	OPEN REFITTED OIL LEAK.	حالة المحرك النظري
03.B Other	UNDER COVER MISSING.	اخرى
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Visual Gear Box Condition	REFITTED OIL LEAK.	حالة الجير النظري
04.B Road Test	NOT CHECK	فحص علي الطريق
<b>05 Suspension System</b>		<b>ممتص الصدمات</b>
05.A Arms	LOWER ARM BUSHES CRACK.	ازرع

DEFECT	REMARKS	
05.B Suspension Subframe	REFITTED.	
<b>06 Seats Condition</b>		<b>المقاعد</b>
06.A Seat Condition	FRONT LEFT REAR COVER LOOSE.	حالة المقاعد
<b>07 Chassis Condition</b>		<b>الشاصي</b>
07.A Chassis	CHECKED ,VISIBLE AREA OK.	الشاسيه
<b>08 Body</b>		<b>جسم المركبة</b>
08.A Trunk	PORTION REPAIRED,REPAINTED	صندوق
08.B Fenders	REAR RIGHT SIDE PORTION REPAIRED,REPAINTED	مدكار
08.C Doors	REAR RIGHT SIDE PORTION REPAIRED,REPAINTED	أبواب
08.D Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
08.E Bonnet	FIRE WALL COVER PORTION DAMAGE.	غطاء المحرك
<b>09 Lights</b>		<b>الاضاءة</b>
09.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.