

Queue Number 2827652

Transaction Date 03 Oct 2026, 13:00:55

Site Name
840 - Emirates AuctionsTransaction Number
52481961 (CC10021) (CC10021)

Vehicle Details

Chassis Number	JM7KFAWL4N*****
Specification	GCC Specification
Make	Mazda
Model	CX 5
Model Year	2022
Color	Silver
Mileage	120894 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR COVERED,CHECKED VISIBLE AREA ONLY	الارضية
01.D Trunk	PORTION REPAINTED,PORTION REPAIRED	صندوق
01.E Sign of back accident		وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED,CHECKED VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	UNDER COVERED,CHECKED VISIBLE AREA ONLY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	UNDER COVERED,MINOR JERKING	الحالة النظرية للجير
04.B Road Test	NOT CHECK	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط

Condition	Remarks	الحالة
06 Brake Condition		الفرامل
06.A Disc&Drum	RUSTY	دسك و طنايبر الفرامل
07 Interior Condition		الحاله الداخليه
07.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
07.B AC Condition	OK	المكيف
07.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للاشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae