



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 14 Oct 2021, 17:48:44 |
| Transaction Number | 80042435 (CC10006) | Queue Number | 312309 |



| | |
|------------------|--------------------------|
| Chassis Number | WBAKB810XBC345423 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | BMW |
| Model | 750LI |
| Model Year | 2011 |
| Color | White |
| Mileage | 0 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 8 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|------------------------------|--|------------------------|
| 01 Body | | جسم المركبة |
| 01.A Paint | BODY PORTION REPAINTED,PORTION REPAIRED | الصبغ |
| 01.B Fenders | REAR LEFT SIDE REPAINTED,PORTION REPAIRED | مدكار |
| 01.C Doors | REAR LEFT REPAINTED&DOOR RUBBER DAMAGED | أبواب |
| 01.D Trunk | MISALIGN | صندوق |
| 01.E Floor | UNDER BODY FULLY COVERED&VISABLE AREA CHECK ONLY &LEFT COVER DAMAGED PART MSSING | الارضية |
| 01.F Bonnet | BONNET SHOCK STAND WEAK NOT WORKING | غطاء المحرك |
| 01.G Bumper | REPAINTED | دعامية |
| 02 Interior Condition | | الحاله الداخليه |
| 02.A AC Condition | OK | المكيف |
| 02.B Roof Ceiling | REAR ROOF CEILING LOSE &REAR WINSHILED CURTAIN NOT WORKING | بطانه السقف |
| 02.C Odometer reading | 211305 km | قراءة عداد المسافات |
| 03 Engine Condition | | المحرك |
| 03.A Engine Condition | MINOR OIL LEAK&UPPER ENGINE COVER NOT FIX PROPERLY | حالة المحرك |

| DEFECT | REMARKS | |
|------------------------------------|---|------------------------|
| 04 Transmission Condition | | الجير |
| 04.A Propeller Shaft | PROPELLER SHAFT FLANGE RUUBER CRACKED,WORNOUT | ناقل الحركة |
| 04.B Gear Box | OK | الجير |
| 04.C Road Test | NOT CHECK | فحص علي الطريق |
| 05 Chassis Condition | | الشاصي |
| 05.A Chassis | VISABLE AREA OK | الشاسيه |
| 06 Seats Condition | | المقاعد |
| 06.A Seat Condition | OK | حالة المقاعد |
| 06.B Seat Belt | OK | حزام الأمان |
| 07 Lights | | الاضاءة |
| 07.A Head Light | OK | الاضاءة الرئيسية |
| 07.B Warning Light | WARNING ON IN DISPLAY | ضوء تحذير |
| 08 Tires and Rims Condition | | الاطارات |
| 08.A Front Tyre | BOTH SIDE 2020 | الاطار الامامي |
| 08.B Rear Tyre | BOTH SIDE 2020 | الاطار الخلفي |
| 08.C Rims Condition | RIMS HAVE SCRATCHES | حالة الجنوط |
| 09 Wipers and Arms | | المساحات |
| 09.A Wiper Arm &Blade | WORN OUT | ازرع المساحات والشفرات |
| 10 Suspension System | | ممتص الصدمات |
| 10.A Arms | FRONT LOWER ARM BUSHES MINOR CRACKED | ازرع |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.