



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 27165285	Plate Category	: PRIVATE
Transaction Date	: 19 JUN 2021 13:02:32	Plate Number	: 278760 EA
Queue Number	: 353379	Import Doc. Ref.	:
Chassis Number	: 3GNFK123X7G278760	Manufacturer/Model	: CHEVROLET/AVALANCHE
Engine Number	:	Model Year	: 2007
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
01 Lights		الانوار
01.04 - Head Lights		الانوار الامامية LEFT SIDE HEAD LIGHT BRACKET DAMAGE
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.04 - Steering Ball Joints, Boots		وصلات عمود عجلة القيادة BALL JOINT BOOTS CRACK
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية TIRES 2020
05 Body		الهيكل
05.01 - Rusty		الصدأ UNDER BODY COMPONENTS RUSTY
05.02 - Paint		الصيغ BODY SCRATCH & DENT
05.08 - Chassis (Frame)		الشاصية CHASSIS RUSTY & BOTH SIDE MIDDLE INNER SIDE MINOR BULGED
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي FRONT WINDSHIELD SPOT CRACK
06 General Items		الاشياء العامة
06.14 - Transmission Condition		حالة ناقل الحركة OIL LEAK & SIGN OF REPAIR
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان OK
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى 297197 KM
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.24 - Digital Display Damaged/Warning Lights		عطل في لوحة التحكم الالكتروني AIR BAG LIGHT ON
09.25 - Body Repainted		أثر صيغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط
تسجيل غير مسئول عن العيوب الخفية

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	N 62197 Dubai Private	
Chassis No :	3GNFK123X7G278760	
Vehicle Make :	CHEVROLET	
Vehicle Model :	AVALANCHE	
Vehicle Class :	Light Vehicle	
Body Type :	PICK-UP	
Fuel :	Benzene	
Color :	Black	
Drive Direction :	--	
Dimensions : (H x W x L) :	-- x -- x --	
Current Odometer :	297205 Kms.	
Origin :	Mexico	Model Year : 2007
Gear Type :	--	Engine Size : 6000 CC
Engine No :	NIL	Horse Power : 310
Axles No :	2	Cylinders : 8
No Of Doors :	4	No Of Seats : 5
G. V. W. :	3000 Kgs.	Empty Weight : 2520 Kgs.

Certificate Number :	1-TAS-2021-14463607	
Inspection Date :	22-06-2021	
Certificate Print Date :	22-06-2021	
Services :	Renewal Test	
Vehicle Testing Partner :	Tasjeel	
Vehicle Testing Center :	Tasjeel Al Aweer	
Total Time Taken :	17 min 25 sec	
Appointment Ref Number :	--	
Start Time :	15:39	End Time : 15:56
Lane :	02	Token No. : 207
Attempt :	1	Prints No : 1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

5400 KM	556 L	901 AED	1.4 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
13 %	0 %	5 %	0.24 %

Vehicle on Petrol HC

Reading
88 PPM VOL

Inspection Remarks:

FRONT BOTH SIDE CHASSIS MID INNER BULGED & FRONT TO REAR BOTH GETTING RUSTY AVOID TO RUST BODY MINOR DENT SCRATCHES // FIX BOTH NUMBER PLATE PROPERLY //

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
34980	VTP Credit Account	14463607	AED 170 Collected on 22/06/2021
Parking Slot No	Service Name	Attempt	Received by
--	Renewal Test	1	Bajurdeen Abdul Gafoor

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

