



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	19 Jan 2023, 15:44:17
Transaction Number	36330406 (CC10010)	Queue Number	657728



Chassis Number	JHMCM56534C413941
Engine Number	
Vehicle Class	Car
Manufacturer	Honda
Model	Accord
Model Year	2004
Color	--
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Rear Tyre	BOTH SIDE 2018 CRACKED , EXPIRED	الاطار الخلفي
01.B Front Tyre	BOTH SIDE 2019 CRACKED,	الاطار الامامي
02 Body		جسم المركبة
02.A Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORTION FADED,PORTION RUSTY	الصبغ
02.B Bumper	MISALIGN,PORTION DAMAGED	دعامية
02.C Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
02.D Bonnet	REFITTED	غطاء المحرك
02.E Vehicle Color	GOLDEN	لون المركبة
03 Chassis Condition		الشاسي
03.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
04 Interior Condition		الحاله الداخليه
04.A Mirror	OUTER COVER DAMAGED	المرايا
04.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
04.C AC Condition	NOT CHECK	المكيف

DEFECT	REMARKS	
04.D Odometer reading	NOT CHECK	قراءة عداد المسافات
04.E Other	CENTER CONSOLE BOX COVER DAMAGED	اخرى
05 Steering Condition		المقود
05.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
05.B Steering Boot	BOOT CUT	ربلة المقود
05.C Steering Oil	OIL LEAK	زيت المقود
05.D Axle	BOOT CUT	اكسلات
06 Transmission Condition		الجير
06.A Road Test	NOT CHECK	فحص علي الطريق
06.B Gear Box Mount	BUSH CUT	كرسي الجير
06.C Visual Gear Box Condition	NOT CHECK,OIL LEAK,REFITTED	حالة الجير النظري
07 Engine Condition		المحرك
07.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK,KEY MISSING,OIL LEAK,REFITTED	حالة المحرك النظري
07.B Mount	BUSH CUT	كرسي
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	LOWER ARM BUSH CUT	ازرع
08.C Other	STABILIZER LINK BOOT CUT	اخرى
08.D Ball Joint	BOOT CUT	مفصل كروي
09 Lights		الاضاءة
09.A Head Light	LENS FADED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية
10 Seats Condition		المقاعد
10.A Seat Condition	COVER PORTION DAMAGED	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.