





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20058031	Plate Category	: PRIVATE
Transaction Date	: 27 JUN 2020 09:53:42	Plate Number	: 022855 EA
Queue Number	: 189523	Import Doc. Ref.	:
Chassis Number	: JTMHT09J395022855	Manufacturer/Model	: TOYOTA/LAND CRUISER
Engine Number	:	Model Year	: 2009
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
01 Lights		الانوار
01.07 - Direction Indicators		انوار مؤشرات الاتجاه FRONT RIGHT SIDE FENDER INDICATOR BROKEN
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.11 - Shock Absorbers		مخمد الصدمات
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية ALL TIRES DOT 2015 EXPIRED
05 Body		الهيكل
05.01 - Rusty		الصدأ UNDER NEATH CHASSIS RUSTY
05.02 - Paint		الصبغ SCRATCHES & DENTS
05.03 - Doors		الابواب LOWER TAIL DOOR NOT OPEN
05.04 - Fenders		المدكار FRONT LEFT SIDE FENDER FRAME & WHEEL HOUSING REPAIRED
05.06 - Roof		السقف SUN ROOF DEFECTIVE , RIGHT SIDE ROOF STAND COVER MISSING
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي FRONT WINDSHEILD MOLDING MISALIGN
05.10 - All Glasses		الزجاج الجانبي وزجاج الابواب FRONT RIGHT SIDE & REAR BOTH SIDE POWER WNDOW NOT WORKING WITH MASTER BUTTON
05.12 - Side Safety Frame		الواقبات الجانبيه BULK HEAD & RADIATOR FRAME REPAIRED , FRONT BODY MOUNT REPAIRED
06 General Items		الاشياء العامة
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها INTERIOR PARTLY WORNOUT



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20058031	Plate Category	: PRIVATE
Transaction Date	: 27 JUN 2020 09:53:42	Plate Number	: 022855 EA
Queue Number	: 189523	Import Doc. Ref.	:
Chassis Number	: JTMHT09J395022855	Manufacturer/Model	: TOYOTA/LAND CRUISER
Engine Number	:	Model Year	: 2009
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

06.14 - Transmission Condition	GEAR OIL LEAK	حالة ناقل الحركة
06.16 - Engine Condition, Smoke	OIL LEAK	حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others	709811 KM . DRIVE HAVE VIBRATION	ملاحظات اخرى
09 Auction		الفحص الكامل
09.06 - Chassis Ok	OK	الشاسي جيد
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.24 - Digital Display Damaged/Warning Lights	AIR BAG LIGHT	عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted	BODY PORTION REPAINTED	أثر صيغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only.		