CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2945827
Transaction Date	05 Nov 2026, 16:45:22
Site Name	840 - Emirates Auctions
Transaction Number	59534075 (CC10008) (CC10011)



Vehicle Details

Chassis Number	JM7TB1MA0G*******
Specification	GCC Specification
Make	Mazda
Model	CX-9
Model Year	2016
Color	White
Mileage	190966 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES	الصبغ
01.C Doors	LEFT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	MISALIGN SCRATCHES	دعامية
01.F Trunk	REPAINTED,REFITTED	صندوق
01.G Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA / OK	الشاسيه
02.B Chassis Number	LEFT SIDE STICKER PORTION DAMAGED	رقم القاعدة
03 Engine Condition		**المحرك**
03.A Other	TOP ENGINE COVER MISSING	اخري
03.B Engine Visual Condition	OIL LEAK ,COMPONENTS REFITTED	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	MINOR JERKING	الحالة النظريه للجير
04.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023 DRY CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 DRY CRACK	الاطار الخلفي
05.C Rims Condition	MINOR SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS GETTING FADED,BRACKET PORTION DAMAGED	الاضاءة الرئيسية
07 Interior Condition		الحاله الداخليه
07.A Mirror	CENTER VIEW MIRROR GETTING FADED	المرايا
07.B AC Condition	OK	المكيف
07.C Power Window Switch And Glass	REAR BOTH SIDE NOT WORKING	مفتاح النافذه و الزجاج
07.D Door Panel	LEATHER PORTION LOOSE	لوحة بطانة الباب
07.E Steering Wheel and control buttons	RELEATHER	عجلة القيادة وازرار التحكم
07.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae