CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2958501
Transaction Date	09 Nov 2026, 13:03:18
Site Name	840 - Emirates Auctions
Transaction Number	52867685 (CC10009) (CC10011)



Vehicle Details

Chassis Number	WAUAYD4L6A*******
Specification	GCC Specification
Make	Audi
Model	Q7
Model Year	2010
Color	Gold
Mileage	208899 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,DENTS SCRATCHES	الصبغ
01.B Doors	REAR RIGHT SIDE REFITTED,DEEP DENTS	أبواب
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS COVERED MUDDY PORTION MINOR DENT	الارضية
01.E Bumper	MISALIGN PORTION CRACK SCRATCHES,TOWING HOOK COVER MISSING	دعامية
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED MUDDY CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK PARTS REFITTED GETTING RUSTY MINOR SHAKING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION WORN OUT CRACK	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS REFITTED MINOR JERKING	الحالة النظريه للجير
05.B Propeller Shaft	CENTER BEARING RUBBER CRACKED	ناقل الحركة
05.C Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Indicator & Hazard light	FRONT LEFT SIDE INDICATOR LIGHT PORTION CRACK	الاشارات
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CONSOLE BOX COVER PORTION DAMAGED PART MISSING	اخري
09.B Mirror	LEFT SIDE LOOSE AUTO FOLDING NOT WORKING BOTH SIDE ADJUSTMENT NOT WORKING PROPERLY & CENTER VIEW MIRROR CASE PORTION CRACK BACK COVER PART MISSING	المرايا
09.C AC Condition	OK,GRILL PORTION DAMAGED	المكيف
09.D Power Window Switch And Glass	REAR RIGHT SIDE NOT WORKING FROM MAIN SWITCH,SWITCH PANEL NOT WORKING PROPERLY & REAR BOTH SIDE CURTAIN MISSING	مفتاح النافذه و الزجاج
09.E Audio	SCREEN FADED,SWITCH PANEL WORN OUT	صوتيات
09.F Sun Visor	LEFT SIDE FABRIC MINOR LOOSE	حاجب الشمس
09.G Odometer reading	CLUSTER DISPLAY PORTION GETTING FADED	قراءة عداد المسافات
09.H Door Panel	REAR RIGHT SIDE CIGARETTE ASHTRAY COVER NOT CLOSE	لوحة بطانة الباب
09.I Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.J Gear Shifting Lever	KNOB,DUST COVER GETTING WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae