

Queue Number 2855886

Transaction Date 10 Oct 2026, 12:46:25

Site Name
840 - Emirates AuctionsTransaction Number
17413270 (CC10013) (CC10025)

Vehicle Details

Chassis Number	1C4RJEAG2K*****
Specification	Imported
Make	Jeep
Model	Grand Cherokee
Model Year	2019
Color	Maroon
Mileage	148130 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	LEFT SIDE BOTH REPAINTED PORTION REPAIRED , FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION GETTING RUSTY	الصبغ
01.C Doors	FRONT BOTH SIDE REPAINTED PORTION REPAIRED , FRONT LEFT SIDE REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION REPAIRED DENT	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED	غطاء المحرك
01.H Trunk	REPAINTED PORTION REPAIRED	صندوق
01.I Fuel Tank	DENT	خزان الوقود
01.J Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD , INNER FENDER FRAME APRON AREA REPAIRED , ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition الشاسي

02.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED OILY DIRTY	الشاسيه
--------------	---	---------

03 Engine Condition المحرك

03.A Engine Visual Condition	MINOR OIL LEAK , OIL PAN DENT , OPEN REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Exhaust System نظام العادم

Condition	Remarks	الحالة
04.A Other	DENT	اخرى
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR JERKING , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص على الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2022 CRACK , RIGHT SIDE 2023	الاطار الخلفي
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Suspension Subframe	MOUNT RUBBER CRACK	ازرع اخرى
08.B Arms	ARM BUSHES CRACK	
08.C Other	SUSPENSION PARTS REFITTED	
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B AC Condition	OK	المكيف
09.C Dash Board	LEATHER REPLACED	لوحة القيادة
09.D Door Panel	PORTION SCRATCHES	لوحة بطانة الباب
09.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae