





### Test Certificate

|                     |                          |                    |            |
|---------------------|--------------------------|--------------------|------------|
| Site Number         | : 840-TASJEEL EM AUCTION | Plate Code         | : 0        |
| Transaction Number  | : 18674790               | Plate Category     | : PRIVATE  |
| Transaction Date    | : 05 DEC 2019 12:05:12   | Plate Number       | : 0775 EA  |
| Queue Number        | : 123542                 | Import Doc. Ref.   | :          |
| Chassis Number      | : WAUDK68T69A010775      | Manufacturer/Model | : AUDI/A 5 |
| Engine Number       | :                        | Model Year         | : 2009     |
| Vehicle Class       | : LIGHT VEHICLE          | Vehicle Color      | : WHITE    |
| Service / Indicator | : DSC AUCTION            |                    |            |

### Statement of Vehicle Condition

| Defect   | Result | Remarks                      |
|--|--------|------------------------------|
| AUTOMATIC TEST:  |        |                              |
| 13 Brake System  |        | الفرامل                      |
| 13.04 - Brake Test   | Passed | فحص الفرامل                  |
| 14 Exhaust Gas Test  |        | الغاز العادم والكربون        |
| 14.01 - Exhaust Gas Test                                   | Passed | فحص الغاز العادم-الكربون     |
| VISUAL TEST:   |        |                              |
| 02 Steering And Suspension System                          |        | عجلة القيادة ونظام التوصيلات |
| 02.05 - Steering Coupling, Column                          |        | ثنائي توصيلة المقود          |
| 02.13 - Stub Axle Assemblies, Boots                        |        | المحور                       |
| 03 Brake System  |        | نظام الفرامل                 |
| 03.01 - Brake Efficiency Front Wheels Left And Right Hands |        | قوة فرامل المحور الامامي     |
| 04 Tires Rims  |        | الاطارات والعجلات            |
| 04.01 - Front Left And Right Hands Tires                   |        | الاطارات الامامية            |
| 04.07 - Rims   |        | الرنجات                      |
| 05 Body  |        | الهيكل                       |
| 05.02 - Paint  |        | الصيغ                        |
| 06 General Items   |        | الاشياء العامة               |
| 06.12 - Seats Condition And Seats Fixing                   |        | المقاعد وحالتها وتثبيتها     |
| 06.14 - Transmission Condition                             |        | حالة ناقل الحركة             |
| 06.16 - Engine Condition, Smoke                            |        | حالة المحرك - الدخان         |
| 07 Remarks   |        | ملاحظات                      |
| 07.04 - Others   |        | ملاحظات اخرى                 |
| 09 Auction   |        | الفحص الكامل                 |
| 09.02 - Need Wheel Alignment                               |        | بحاجة الى ميزانية العجلات    |
| 09.06 - Chassis Ok   |        | الشاصي جيد                   |
| 09.14 - Sign Of Front Accident                             |        | أثر حادث في مقدمة المركبة    |
| 09.15 - Sign Of Rear Accident                              |        | أثر حادث في مؤخرة المركبة    |
| 09.18 - A/C Not Cooling                                    |        | عطل في المكيف                |



### Test Certificate

|                     |                          |                    |            |
|---------------------|--------------------------|--------------------|------------|
| Site Number         | : 840-TASJEEL EM AUCTION | Plate Code         | : 0        |
| Transaction Number  | : 18674790               | Plate Category     | : PRIVATE  |
| Transaction Date    | : 05 DEC 2019 12:05:12   | Plate Number       | : 0775 EA  |
| Queue Number        | : 123542                 | Import Doc. Ref.   | :          |
| Chassis Number      | : WAUDK68T69A010775      | Manufacturer/Model | : AUDI/A 5 |
| Engine Number       | :                        | Model Year         | : 2009     |
| Vehicle Class       | : LIGHT VEHICLE          | Vehicle Color      | : WHITE    |
| Service / Indicator | : DSC AUCTION            |                    |            |

#### Statement of Vehicle Condition

|  |   |                               |
|--|---|-------------------------------|
| 09.24 - Digital Display Damaged/Warning Lights                             | SERVICE REQD/ LOW WASHER FLUID<br>MESSAGES ON | عطل في لوحة التحكم الالكتروني |
| 09.25 - Body Repainted   | BODY PORTIONS REPAINTED                       | أثر صيغ في المركبة            |
| The Test Certificate Shows the test Result at the time of inspection only. |   |                               |