

Queue Number

2646200

Transaction Date

13 Aug 2026, 13:47:20

Site Name

840 - Emirates Auctions

Transaction Number

32877231 (CC10006) (CC10006)



Vehicle Details

Chassis Number

LSJA36U9XR*****

Specification

GCC Specification

Make

MG

Model

GT

Model Year

2024

Color

Black

Mileage

59130 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENT & SCRATCHES	الصبغ
01.B Doors	LEFT SIDE BOTH REPAINTED, PORTION REPAIRED	أبواب
01.C Rusty	UNDER BODY PARTS, SUSPENSION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR THICK RUST PROOFED, PORTION DENT	الارضية
01.E Sign of side accident		وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	COVERD, CHECKED VISIBLE AREA ONLY, OK	الشاسيه
--------------	---------------------------------------	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	SHAKING,PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	-----------------------------	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	MINOR JERKING,PARTS GETTING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECK	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي

Condition	Remarks	الحالة
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
07 Interior Condition		الحالة الداخليه
07.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
07.B AC Condition	OK	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae