



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **17 May 2023, 17:03:01**  
 Transaction Number **75581046 (CC10010)** Queue Number **716382**



Chassis Number **MDHBN7AD6DG020285**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Nissan**  
 Model **Sunny**  
 Model Year **2013**  
 Color **White**  
 Mileage **001 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **4**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Suspension System</b>		<b>ممتص الصدمات</b>
01.A Arms	LOWER ARM BUSHES CRACKED .	ازرع
01.B Shock Absorber	LEAK ,WEAK .	ممتص الصدمات
<b>02 Steering Condition</b>		<b>المقود</b>
02.A Steering Box	OIL LEAK .	جهاز المقود
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Road Test	NOT CHECKED .	فحص علي الطريق
03.B Visual Gear Box Condition	NOT CHECKED ,REFITTED OIL LEAK.	حالة الجير النظري
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,REFITTED .OIL LEAK.	حالة المحرك النظري
<b>05 Body</b>		<b>جسم المركبة</b>
05.A Other	FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED & REAR VBUMPER FRAME ,BACK PANEL ,QUARTER PANEL REPAIRED.	اخرى
05.B Sign of front accident		وجود مؤشر لحادث في المقدمة

DEFECT	REMARKS	
05.C Floor	PORTION DENT .	الارضية
05.D Paint	BODY PORTION REPAIRED ,PORTION REPAINTED ,DENTS SCRATCHES .	الصبغ
05.E Sign of back accident		وجود مؤشر لحادث في الخلف
05.F Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY	صدأ
05.G Bumper	MISALIGN ,SCRATCHES .	دعامية
<b>06 Chassis Condition</b>		<b>الشاسي</b>
06.A Chassis	FRONT LEFT SIDE CHASSIS END & REAR LEFT SIDE CHASSIS EXTENSION DENT DENT ,KINK .	الشاسيه
<b>07 Tires and Rims Condition</b>		<b>الاطارات</b>
07.A Rear Tyre	BOTH SIDE 2020 CRACKED .	الاطار الخلفي
07.B Front Tyre	BOTH SIDE 2020 CRACKED .	الاطار الامامي
<b>08 Interior Condition</b>		<b>الحاله الداخليه</b>
08.A Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
08.B Odometer reading	NOT CHECKED .	قراءة عداد المسافات
08.C AC Condition	NOT CHECKED.	المكيف
<b>09 Lights</b>		<b>الاضاءة</b>
09.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.