



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	11 Aug 2022, 17:52:33
Transaction Number	60316413 (CC10006)	Queue Number	312309



Chassis Number	JN8BY15YOYX450552
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2000
Color	Gold
Mileage	435812 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY TOTALLY REPAINTED , PORTION REPAIRED , MINOR DENT SCRATCHES(VEHICLE COLOR CHANGE GOLDEN TO SILVER)	الصبغ
01.B Pillars	LEFT SIDE PILLAR ROOFRAILL REPAIRED	القوائم
01.C Bonnet	REFITTED	غطاء المحرك
01.D Floor	WASH UNDER FLOOR TOO MUDDY OILY	الارضية
01.E Sign of back accident		وجود مؤشر لحادث في الخلف
01.F Sign of side accident		وجود مؤشر لحادث في الجانب
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	MINOR OIL LEAK REFITTED , JERKING	حالة الجير النظرى
02.C Gear Box Mount	MOUNT RUBBER CUT	كرسي الجير
02.D DIFFERENTIAL	OIL LEAK	الدفرنشئل
03 Interior Condition		الحاله الداخليه
03.A AC Condition	OK	المكيف
03.B Roof Light	SUNGLASSES BOX DAMAGED	أنارة السقف

DEFECT	REMARKS	
03.C Other	GEAR SHIFTING LEVER DUST COVER DAMAGED	اخرى
03.D Dash Board	PORTION CRACKED, LOOSE	لوحة القيادة
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
05 Seats Condition		المقاعد
05.A Seat Condition	SEATS HAVE EXTRA COVER	حالة المقاعد
06 Engine Condition		المحرك
06.A Visual Engine Condition	MINOR OIL LEAK REFITTED, ABNORMAL NOISY SHAKING	حالة المحرك النظري
07 Suspension System		ممتص الصدمات
07.A Arms	CONTROL ARM BUSHES CRACKED	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
07.C Other	STABILIZER LINK BOOT CUT	اخرى
08 Chassis Condition		الشاسي
08.A Chassis	PORTION MINOR RUSTY, OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.