CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2941202	Transaction Date	04 Nov 2026, 16:46:50
Site Name	840 - Emirates Auctions	Transaction Number	50079998 (CC10026) (CC10026)



Vehicle Details

Chassis Number	1FM5K8D80D*******
Specification	GCC Specification
Make	Ford
Model	Explorer
Model Year	2013
Color	Grey
Mileage	279242 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES , PORTION FADED	الصبغ
01.C Doors	BOTH SIDE LEFT REPAINTED PORTION REPAIRED , FRONT LEFT SIDE OUTER A PILLAR COVER DAMAGE	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR BADLY DENT , MUDDY	الارضية
01.F Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED , REFITTED	غطاء المحرك
01.H Trunk	REPAINTED PORTION REPAIRED , MISALIGN	صندوق
01.I Door Handle &Lock	LEFT SIDE LOCK HANDLE DAMAGE	مقابض الأبواب والأقفال
01.J Sign of back accident	BACK PANEL , BUMPER FRAME REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis Extension	BOTH SIDE CHASSIS EXTENSION END PORTION DENT	تمديدات الشاسي
02.B Chassis	CHASSIS PORTION COVER , CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	ENGINE NOT START , ALL SYSTEM NOT CHECK , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**

Condition	Remarks	الحالة
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECK , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED , ALL LIGHT NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CONSOLE BOX PORTION WORN OUT , INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
09.B AC Condition	NOT CHECK	المكيف
09.C Door Panel	PORTION DAMAGE	لوحة بطانة الباب
09.D Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
09.E Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
10 Battery Condition		حالة البطارية
10.A Battery Condition	MISSING	حالة البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae