

## **TEST CERTIFICATE**

الحاله الداخلية

الاطارات

الجير

Site Number Transaction Number **840-Emirates Auctions** 

10687544 (CC10006)

Transaction Date 05 May 2022, 16:08:02

Queue Number 312309

Chassis Number

WP0ZZZ98Z2U640427

Car

Blue

Engine Number

Vehicle Class

Manufacturer **Porsche** 

Model **Boxster** 

2002 Model Year

Color

199496 Km Mileage

Fuel Type **Petrol** 

No. Of Cylinders

Specification **GCC Specification** 

**REMARKS DEFECT** 

01 Lights	الاضاءة

01.A Head Light HEAD LIGHT SWICH NOT WORKING PROPERLY الاضاءة الرئيسية WARNING LIGHT ON IN DISPLAY 01.B Warning Light ضوء تحذير

## **02 Interior Condition**

02.A Power Window Switch	NOT WORKING	مفتاح النافذه
02.B AC Condition	NOT WORKING	المكيف
02.C Sunroof	CONVERTIBLE ROOF NOT WORKING	فتحت سقف

02.D Sun Visor **GLASS COVER MISSING** حاجب الشمس 02.E Door Panel RIGHT INNER MIRROR COVER MISSING لوحة بطانة الباب

## **03 Tires and Rims Condition**

BOTH SIDE 2018/2016 EXPIRED & CRACKED 03.A Rear Tyre الاطار الخلفى 03.B Front Tyre BOTH SIDE 2016 CRACKED, EXPIRED الاطار الامامى

## **04 Transmission Condition**

04.A Road Test **NOT CHECK** فحص علي الطريق 04.B Visual Gear Box **REFITTED & JERKING** حالة الجير النظرى Condition

DEFECT	REMARKS	
05 Engine Condition		المحرك
05.A Visual Engine Condition	MINOR OIL LEAK , REFITTED & RPM NOT WORKING PROPERLY	حالة المحرك النظرى
06 Chassis Condition		الشاصي
06.A Chassis	OK	الشاسيه
07 Body		جسم المركبة
07.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENT, SCRATCHES	الصبغ
07.B Fenders	RIGHT SIDE BOTH FENDER REPAINTED, PORTION REPAIRED	مدكار
07.C Pillars	RIGHT SIDE B/PILLAR REPAIRED	القوائم
07.D Doors	RIGHT SIDE REPAINTED, REPAIRED	أبواب
07.E Sign of side accident		وجود مؤشر لحادث في الجانب

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
  Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.