



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **03 Aug 2022, 18:03:23**
 Transaction Number **88733460 (CC10006)** Queue Number **312309**



Chassis Number **1GKEV33D69J113972**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **GMC**
 Model **Acadia**
 Model Year **2009**
 Color **White**
 Mileage **224644 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **6**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES ON BODY PORTION RUSTY	الصبغ
01.B Roof	REPAINTED	السقف
01.C Fenders	PORTION REPAIRED,REPAINTED	مدكار
01.D Doors	PORTION REPAIRED,REPAINTED	أبواب
01.E Trunk	PORTION REPAIRED,REPAINTED	صندوق
01.F Bonnet	STAND MISSING & PORTION REPAIRED REPAINTED, REFITTED	غطاء المحرك
01.G Sign of side accident		وجود مؤشر لحادث في الجانب
01.H Other	FRONT FENDER FRAME, RADITOR SUPPORT , BULK HEAD REPAIRED	اخرى
01.I Windshield	FRONT SPOT CRACKED	زجاج
02 Interior Condition		الحالة الداخلية
02.A AC Condition	NOT WORKING	المكيف
02.B Sunroof	CURTAIN LOOSE	فتحة سقف
02.C Door Panel	FRONT LEFT SIDE COVER PORTION DAMAGED	لوحة بطانة الباب
02.D Dash Board	CENTER CONSOLE BOX COVER LOCK NOT WORKING	لوحة القيادة

DEFECT	REMARKS	
03 Engine Condition المحرك		
03.A Visual Engine Condition	OIL LEAK , REFITTED & ABNORMAL NOISY	حالة المحرك النظري
04 Lights الاضاءة		
04.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
05 Wipers and Arms المساحات		
05.A Wiper Arm &Blade	REAR MISSING	ازرع المساحات والشفرات
06 Transmission Condition الجير		
06.A Road Test	NOT CHECK	فحص علي الطريق
06.B Visual Gear Box Condition	REFITTED	حالة الجير النظري
07 Suspension System ممتص الصدمات		
07.A Arms	LOWER ARM BUSH CRACKED	ازرع
08 Tires and Rims Condition الاطارات		
08.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
09 Chassis Condition الشاسي		
09.A Chassis	FRONT LEFT SIDE CHASSIS BEND	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	--
Chassis No :	1GKEV33D69J113972
Vehicle Make :	GMC
Vehicle Model :	ACADIA
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	224649 Kms.
Origin : United States	Model Year : 2009
Gear Type : Automatic	Engine Size : 3600 CC
Engine No : NIL	Horse 288
Axles No : 2	Power :
No Of 4	Cylinders : 6
Doors :	No Of Seats : 8
G. V. W. : 3175 Kgs.	Empty 2234 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17382027		
Inspection Date :	10-08-2022		
Certificate Print Date :	11-08-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	12 min 0 sec		
Appointment Ref Number :	--		
Start Time :	13:38	End Time :	13:50
Lane :	03	Token No. :	164
Attempt :	1	Prints No. :	1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
2 %	2 %	10 %	0.01 %
Vehicle on Petrol HC Reading			
4 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Engine change engine upper mounting crack	Mounting modified or repositioned	Major
Engine repair oil leak	Oil leaking continuously	Major
Tinted remove dark tinted	Dark	Major

Inspection Remarks: bulkhead/front left side fender frame repaired front left side frame member inner skirt minor dent

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
6831	Cash	17382027	AED 170 Collected on 11/08/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

