



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	25 Nov 2021, 18:01:20
Transaction Number	79166825 (CC10006)	Queue Number	312309



Chassis Number	JTDBW923791153761
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Yaris
Model Year	2009
Color	White
Mileage	429806 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY TOTALY REPAINTED & PORTION REPAIRED	الصبغ
01.B Other	FRONT RADIATOR LOWER SUPPORT MINOR BEND & REAR QUATER PANEL REPAIRED	اخرى
01.C Bumper	REPAINTED, LOOSE	دعامية
01.D Rusty	UNDER BODY PART , CHASSIS , FLOOR GETTING MINOR RUSTY	صدأ
02 Chassis Condition		الشاسي
02.A Chassis	FRONT RIGHT SIDE CHASSIS MINOR DENT	الشاسيه
03 Engine Condition		المحرك
03.A Engine Condition	OPEN, REFITIED, OIL WET	حالة المحرك
03.B Other	ENGINE NOT START ALL SYSTEM NOT CHECK	اخرى
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Gear Box	REFITIED	الجير
05 Seats Condition		المقاعد

DEFECT	REMARKS	
05.A Seat Belt	OK	حزام الأمان
05.B Seat Condition	FRONT SEAT CUT & SEAT DIRTY	حالة المقاعد
06 Wipers and Arms		المساحات
06.A Wiper Arm & Blade	WORNOUT	ازرع المساحات والشفرات
07 Lights		الاضاءة
07.A Head Light	BRACKET BROKEN & LENS FADED	الاضاءة الرئيسية
08 Tires and Rims Condition		الاطارات
08.A Front Tyre	BOTH SIDE 2018,PUNCHER	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2018,PUNCHER	الاطار الخلفي
08.C Rims Condition	RIMS HAVE MINOR SCRATCHES & DENTS	حالة الجنوط
09 Interior Condition		الحالة الداخليه
09.A AC Condition	NOT CHECK	المكيف
09.B Other	INTERIOR DIRTY&CENTER CONSOLE BOX COVER DAMAGED	اخرى
09.C Mirror	RIGHT SIDE COVER BROKEN	المرآيا
09.D Door Panel	RIGHT SIDE PAD BROKEN	لوحة بطانة الباب
10 Suspension System		ممتص الصدمات
10.A Shock Absorber	REAR LEFT SIDE LEAK	ممتص الصدمات
10.B Arms	REAR CONTROL ARM BUSHES CRACKED	ازرع
11 Steering Condition		المقود
11.A Tie Rod End	BOOT CUT	مؤخرة الرودادات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.