



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>24 Nov 2021, 18:40:32</b>
Transaction Number	<b>87116338 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>WPOZZZ97ZCL000204</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Porsche</b>
Model	<b>Panamera</b>
Model Year	<b>2012</b>
Color	<b>White</b>
Mileage	<b>135206 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		<b>الاطارات</b>
01.A Front Tyre	BOTH SIDE 2019 & CRACKED	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2019 CRACKED	الاطار الخلفي
01.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
<b>02 Chassis Condition</b>		<b>الشاسي</b>
02.A Chassis	VISABLE AREA OK	الشاسيه
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Floor	UNDER BODY FULLY COVERED	الارضية
03.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED	الصبغ
03.C Doors	REAR RIGHT SIDE PORTION REPAINTED,REPAIRED	أبواب
03.D Fenders	REAR RIGHT SIDE &FRONT BOTH SIDE PORTION REPAINTED	مدكار
03.E Trunk	INNER CURTAIN MISSING	صندوق
<b>04 Seats Condition</b>		<b>المقاعد</b>
04.A Seat Belt	OK	حزام الأمان
04.B Seat Condition	OK	حالة المقاعد
<b>05 Engine Condition</b>		<b>المحرك</b>

DEFECT	REMARKS	
05.A Engine Condition	SIGN OF MINOR OIL LEAK&ABNORMAL NOSIY	حالة المحرك
<b>06 Transmission Condition</b>		<b>الجير</b>
06.A Road Test	NOT CHECK	فحص علي الطريق
06.B Gear Box	OK	الجير
<b>07 Wipers and Arms</b>		<b>المساحات</b>
07.A Wiper Arm &Blade	WORNOUT&LEFT SIDE LOOSED	ازرع المساحات والشفرات
<b>08 Interior Condition</b>		<b>الحالة الداخليه</b>
08.A AC Condition	OK	المكيف
08.B Dash Board	RIGHT SIDE FOUSE COVER MISSING	لوحة القيادة
08.C Other	REAR CONSOLE BOX COVER MISSING	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.